

ASS. REC. BY:

REF:

C721 22 0014721K

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 9612 Yr Regn: 09. 19

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel c.c. 1496

Colour

M.D Blue

A/C: Insured / Std / NI / NA

Sp. Reading

162742

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU3 1324724

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

Interlac 215/60R16

R: Runwide

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

2

mm

D.O.A.

14/2/22

D.O.I.

18/2/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LUMP SUM \$1150, 3DAYS

RED: 6256.64; 84%

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Date: 14/02/2022

Vehicle No: SMN9612Y

Model: HONDA VEZEL HYBRID 1.5X

Chassis: RU31324724

Reg.Year: 2018

Third Party Insurer: CHINA TAIPING

Third Party Veh No: SMQ1004P

Date of Accident: 14/02/2022

Estimator: KIT

Surveyor:

Not Authorised
Recovery By claim

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH	1	12	\$1,723.50
2	FRONT HEADLAMP LOWER BRACKET LH	1	12	\$55.60
3	FRONT BUMPER	1	12	\$817.90
4	FRONT BUMPER SIDE RETAINER LH	1	12	\$33.90
5	FRONT FENDER LH	1	12	\$548.60
6	FRONT FENDER "HYBRID" EMBLEM LH	1	12	\$57.40
7	FRONT FENDER INNER SHIELD LH	1	12	\$134.60
8	FRONT WHEEL ARCH GARNISH LH	1	12/100	\$175.70
9	FRONT ALLOY RIM LH	1	12	\$1,650.00
10	FRONT SHOCK ABSORBER LH	1	12	\$351.50
11	FRONT KNUCKLE ARM LH	1	12	\$243.50
12	FRONT WHEEL BEARING LH	1	12	\$152.10
13	FRONT LOWER ARM LH	1	12	\$351.50
14	FRONT DOOR SIDE MIRROR COVER LH	1		REPAIR
15	FRONT DOOR LH	1		REPAIR
SUB TOTAL				\$6,295.80
LESS 20%				\$1,259.16
PARTS TOTAL				\$5,036.64

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	12	\$50.00
2	FRONT FENDER INNER SHIELD CLIPS LH	1	12	\$20.00
3	FRONT TYRE LH - 215/60R16	1	12	\$250.00
4	FRONT WHEEL ARCH GARNISH CLIPS LH	1	12	\$20.00
S/N TOTAL				\$340.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 14/02/2022
Vehicle No: SMN9612Y
Model: HONDA VEZEL HYBRID 1.5X
Chassis: RU31324724
Reg.Year: 2018

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SMQ1004P
Date of Accident: 14/02/2022
Estimator: KIT
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST LEFT ACCIDENT AREAS & ETC.

2001
\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.

4001
\$700.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

nn \$100.00 X

TO WHEEL ALIGNMENT & BALANCING

nn \$100.00 X

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

nn \$100.00 X

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER LH, FRONT KNUCKLE ARM LH, FRONT LOWER ARM LH & ETC.

nn \$250.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 101

LABOUR TOTAL \$2,030.00

KIT

TOTAL \$7,406.64

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 14/02/2022 14:19 (SGT)
Date of Accident 14/02/2022 09:30 (SGT)
Exact Location of Accident KPE, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMN9612Y

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner 1NSPIRED EMPIRE AUTO LEASING PTE LTD
Company Reg No 2XXXXXX323H
Email Address winnie1nspired2@gmail.com
Mobile Phone No (Phone) +65-93403154
Alternative Phone No (Office) +65-93403154

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1496

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number 5112288879-02
Cover Note Number -

DRIVER

Name of Driver LIM KOK CHUAN
NRIC No SXXXX486E

