

Date: 14/02/2022

Vehicle No: SMN9612Y

Model: HONDA VEZEL HYBRID 1.5X

Chassis: RU31324724

Reg. Year: 2018

Third Party Insurer: CHINA TAIPING

Third Party Veh No: SMQ1004P

Date of Accident: 14/02/2022

Estimator: KIT

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH	1	Re	\$1,723.50
2	FRONT HEADLAMP LOWER BRACKET LH	1	Re	\$55.60
3	FRONT BUMPER 782.70	1	My car Re	\$817.90
4	FRONT BUMPER SIDE RETAINER LH	1	Re	\$33.90
5	FRONT FENDER LH	1	Re	\$548.60
6	FRONT FENDER "HYBRID" EMBLEM LH	1	Re	\$57.40
7	FRONT FENDER INNER SHIELD LH	1	Re	\$134.60
8	FRONT WHEEL ARCH GARNISH LH	1	Re/low	\$175.70
9	FRONT ALLOY RIM LH	1	Re	\$1,650.00
10	FRONT SHOCK ABSORBER LH	1	Re	\$351.50
11	FRONT KNUCKLE ARM LH	1	Re	\$243.50
12	FRONT WHEEL BEARING LH	1	Re	\$152.10
13	FRONT LOWER ARM LH	1	Re	\$351.50
14	FRONT DOOR SIDE MIRROR COVER LH	1		REPAIR
15	FRONT DOOR LH	1		REPAIR
SUB TOTAL				\$6,295.80
LESS 20%				\$1,259.16
PARTS TOTAL				\$5,036.64

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	Re	\$50.00
2	FRONT FENDER INNER SHIELD CLIPS LH	1	Re	\$20.00
3	FRONT TYRE LH - 215/60R16	1	Re	\$250.00
4	FRONT WHEEL ARCH GARNISH CLIPS LH	1	Re	\$20.00
S/N TOTAL				\$340.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer

Signature:

Head Office

8 Rong Chong Road Singapore 156143

Tel: (65) 6479 1913 | Fax: (65) 6479 9110

Branch

8A Serangoon North Ave 5 Singapore 554800

Tel: (65) 6484 8810 | Fax: (65) 6481 1993

Branch (Motor Insurance Claims)

100 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (65) 6481 1022 | Fax: (65) 6481 1011



Date: 14/02/2022
Vehicle No: SMN9612Y
Model: HONDA VEZEL HYBRID 1.5X
Chassis: RU31324724
Reg.Year: 2018

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SMQ1004P
Date of Accident: 14/02/2022
Estimator: KIT
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST LEFT ACCIDENT AREAS & ETC.

2000
\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.

4000
\$700.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

na \$100.00 X

TO WHEEL ALIGNMENT & BALANCING

na \$100.00 X

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

na \$100.00 X

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER LH, FRONT KNUCKLE ARM LH, FRONT LOWER ARM LH & ETC.

na \$250.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 100

LABOUR TOTAL \$2,030.00

KIT

TOTAL \$7,406.64

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9010 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

