Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)

Sent: Wednesday, 16 February 2022 5:43 PM

To: service@kkimhin.com.sg; survey@kkimhin.com.sg

Cc: SUR

Subject: LPC-OD SMP 3517T DOA: DOA: 13/02/2022

Dear Simon/Meng Huat,

As instructed by our client, please proceed to repair the insured vehicle SMP 3517T (Excess \$0/-).

Kindly provide us the SMP 3517T GIA report.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)