

Veron Chen (LKKAUTO)

From: Steve Chen (LKK Auto)
Sent: Thursday, 24 February 2022 10:24 PM
To: Carine Yeo TCBC
Cc: Veron Chen (LKKAUTO)
Subject: SMJ 6678 Z - FINAL BILL
Attachments: SMJ 6678 main estimate.pdf; SMJ6678Z_FINAL BILL.pdf

Hi Carine,

We will be advising our Principal a cost of repair of \$4066.50 (P/P before GST) - with 3 days of repair, subject to their approval.

Thanks.

Best Regards,
Steve Chen | Automotive Assessor
LKK Auto Consultants Pte Ltd
Phone: 81117723/6256-3561 | email: stevenfoong@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


From: Carine Yeo TCBC <carine.yeo@borneomotors.com.sg>
Sent: Thursday, 24 February 2022 3:12 pm
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Subject: SMJ 6678 Z - FINAL BILL

Good afternoon Steve,

With reference to the above-mentioned.


I have attached a copy of the Final Bill for your immediate attention.

Repair Amount : \$ 4065.50 + GST \$284.66 = \$4351.16
Days of Repair : 03 working days

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	4,066.50
	Please acknowledge receipt of vehicle	Parts	1,663.00	
		Labour	2,307.50	
		Sublet	96.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
			GST 7.00%	284.66
			Less	0.00
			Amount Due	4,351.16

Need to replace this ? item

No 14 - L52162-76040 - Plate, rear bumper - \$18.40



Thank you and Best Regards

Carine Yeo
Motor Claims Assessor

DIRECT LINE +65 6631 1505 | MOBILE +65 9699 6192 | FAX +65 6476 6247

EMAIL: carine.yeo@borneomotors.com.sg

Inchcape – Borneo Motors | 2 Pandan Crescent, S128462

www.borneomotors.com.sg | www.lexus.com.sg