

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EG122001506/EQF3E2

**Date:** 01/03/2022

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** FX9025Y

**Insured Vehicle No :** PC9731J

Date of Loss: 11/02/2022

Nature of Claim:

TP

Claim No: CDMFG22000289

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FX9025Y**

Make & Model: HONDA WAVE 125-S, 125cc

Engine No: NF125MDE0092286

Reg. Date: 29/03/2004 (Man. Year: 2004)

Chassis No: NF125MD0092286

Colour: Blue

Odometer: 0 km

Engine Capacity: 125 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size:

80/90-17

Front Left Side: Goodyear 4 mm

Rear Left Side:

Goodyear 4 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,525.00	1,071.90	453.10	29.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	225.00	195.00	30.00	13.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,750.00</b>	<b>1,266.90</b>	<b>483.10</b>	<b>27.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>950.00</b>		
<b>Nett Amount (S\$)</b>	<b>1,750.00</b>	<b>950.00</b>	<b>800.00</b>	<b>45.71</b>

### INSPECTION

Date of Assignment: 16/02/2022

Date Inspected: 16/02/2022

Inspected At:

Kim Kock Motor Pte Ltd (HQ)

Blk 27A Jurong Port Road #01-19

Singapore 619101

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Mar 2022)	
Parts:	N/A	HONDA WAVE 125-S 125cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FX9025Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*UPPER BRACKET	Bent	195.00 F	*195.00 FL
2	1		*CONE BEARING	Necessary	95.00 F	*95.00 FL
3	1		*HANDLE BAR	Bent	85.00 F	*85.00 FL
4	1		*HANDLE BALANCER	Not Necessary	38.00 F	*- FL
5	1		*(R) MIRROR	Broken	38.00 F	*38.00 FL
6	1		*(R) SIGNAL LIGHT	Broken	58.00 F	*58.00 FL
7	1		*HAND LIGHT	Cracked	68.00 F	*68.00 FL
8	1		*BRAKE PUMP	Not Necessary	95.00 F	*- FL
9	1		*BRAKE LEVER	Not Necessary	28.00 F	*- FL
10	1		*HAND LIGHT COVER	Broken	78.00 F	*78.00 FL
11	1		*METER REAR COVER	Not Necessary	78.00 F	*- FL
12	2		*SIDE COVER R/L	Broken	190.00 F	*190.00 FL
13	1		*FRONT FENDER COVER	Broken	48.00 F	*48.00 FL
14	1		*NO PLATE	Bent	25.00 F	*25.00 FL
15	1		*FRONT MUDGUARD	Broken	78.00 F	*78.00 FL
16	1		*FRONT INNER SIDE BLACK COVER	Broken	38.00 F	*38.00 FL
17	1		*FRONT SPORT RIM	Bent	195.00 F	*195.00 FL
18	1		*FRONT BRAKE DISH	Not Necessary	95.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,525.00	1,191.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	119.10
Total Parts (\$\$)	1,525.00	1,071.90

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	45.00	45.00
2	LABOUR	New	180.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>225.00</b>	<b>195.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >