

PK 9025 Y
W 125

ERGO Insurance
TP-claim.

Towbar — \$45 / (nett)
Upper Bracket — \$195 ? / BT
con Bearing — \$95 - ? / nec
Hender Bal — \$85 - / RT
Hender Beleser — \$38 X NN
(E) mirror — \$38 - / BR
(P) Signal Right — \$58 - / BR
Head Right — \$68 - / CRA
Brake pump — \$95 - X NN
Brake lever — \$28 - X NN
Head Right cover — \$78 - ? / BR
meter Rear cover — \$78 - X NN
Slider cover P/L — \$190 - / BR
Front sender cover — \$48 - / BR
No plate — \$25 - / RT
Front Mangung — \$78 - / BR
Front IN Slider Black cover — \$38 - / BR
Front Sepat Rim — \$195 - / BT

P = 1191
-10%
1071.90

L + n = 195
1266.90

L/S - 950

Rony Brake Dish — ~~95~~ × ~~AT \$50 m~~
(abnanc — ~~180~~ \$150 / (nett)

Steve (LKK)

16/2/22, 4.30pm

m m

L/S

My AL by
3 dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: