



TEL: 6256 3561 FAX: 6256 4315

Req. No: 199607198R GST Req. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS3/AIS22001531/Vvf3 Date: 17/02/2022 Code: AIS	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
	<b>Insured Veh.</b>	SLQ 564H	<b>Veh. Inspected</b>	FBM 3918R
	<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	933MAISCL2022 00004FQ	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	SHANTI	<b>Assign Date</b>	17/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>		<b>c.c</b>	0
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
	<b>Chassis No.</b>		<b>Colour</b>	
	<b>Odometer</b>	-	<b>Steering</b>	
	<b>Brakes</b>		<b>Modification</b>	
	<b>General</b>			
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>			mm
	<b>L/H Front Tyre</b>			mm
	<b>R/H Rear Tyre</b>			mm
	<b>L/H Rear Tyre</b>			mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
	<b>Accident Date</b>	24/01/2022	<b>Inspection Date</b>	17/02/2022
	<b>Survey held at</b>	ONG MOTOR TRADING NO. 464 MACPHERSON ROAD SINGAPORE 368182		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			