



55 UBI ROAD 1 SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0104/2022/JT
DATE : 15-Feb-22
WIP : 11634

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS DHARMARAJ MELANCIA SNEGA LATHA
ADDRESS : 31 BEDOK SOUTH AVENUE 5
#19-307
SINGAPORE 460031
TELEPHONE : HP +65 87823250
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900009059-03
VEHICLE NO : **SMH 7690 R**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 30/1/2019
ENGINE NO : CVK 075880
CHASSIS NO : WAUZZZF43KA029160
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Feb-22
PLACE OF ACCIDENT : BEDOK SOUTH AVENUE 2 CAR PARK



55 UBI ROAD 1, SINGAPORE 408699

TEL 6356 2323 FAX 6841 1183

EMAIL: NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 7690 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACCUM AND REGAS.	S/N \$ 1,400.00 x	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED.	\$ 4,200.00 1000	
5	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00 1100	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 8,622.00	

PREMIUM AUTOMOBILES

55, UBI ROAD 1, SINGAPORE 408690

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHALE@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

55, UBI ROAD 1, SINGAPORE 408690

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHALE@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 7690 R

ESTIMATED LABOUR CHARGES FOR

TS & PRICES

DAMAGED PARTS & PRICES

REMARKS	S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1		FRONT BUMPER <i>Rehd</i>	1	\$ 1,787.00	<i>x</i>
2		FRONT BUMPER FIXING PARTS <i>Neu</i>	1	\$ 612.00	<i>x</i>
3		FRONT BUMPER SECURING STRIP <i>?</i>	2	\$ 79.00	<i>?</i>
4		FRONT BUMPER GRILLE - CENTER <i>cracked</i>	1	\$ 219.00	<i>✓</i>
5		FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>?</i>	1	\$ 254.00	<i>?</i>
6		FRONT BUMPER AIR GUIDE - RH <i>Neu</i>	1	\$ 72.00	<i>x</i>
7		RADIATOR GRILLE <i>cracked</i>	1	\$ 1,478.00	<i>✓</i>
8		FRONT BUMPER AIR GUIDE GRILLE - RH <i>Neu</i>	1	\$ 151.00	<i>x</i>
9		FRONT BUMPER FOAM FILLER PIECE <i>Neu</i>	1	\$ 139.00	<i>x</i>
10		FRONT BUMPER REINFORCMENT BEAM <i>Neu</i>	1	\$ 899.00	<i>x</i>
11		FRONT BUMPER BRACKET - RH <i>Neu</i>	1	\$ 254.00	<i>x</i>
12		FRONT BUMPER GUIDE SECTION - RH <i>Neu</i>	1	\$ 41.00	<i>x</i>
13		FRONT BUMPER TOP COVER <i>Neu</i>	1	\$ 143.00	<i>x</i>
14		"CAUTION" STICKER <i>Neu</i>	1	\$ 16.00	<i>x</i>
15		AIR COND STICKER <i>Neu</i>	1	\$ 9.00	<i>x</i>
16		FRONT BUMPER BRACKET LOCK CARRIER <i>?</i>	1	\$ 154.00	<i>?</i>
17		FRONT BUMPER SUPPORT - LH / RH <i>Neu</i>	2	\$ 64.00	<i>x</i>
18		POP RIVET <i>Neu</i>	4	\$ 4.00	<i>x</i>
19		FRONT PARKING AID SENSOR - INNER / OUTER <i>Neu</i>	2	\$ 244.00	<i>x</i>
20		FRONT BUMPER PARKING AID SENSOR SEAL RING <i>Neu</i>	4	\$ 10.00	<i>x</i>
SUB TOTAL SPARE PARTS			:	\$ 6,629.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

ADD-1 SINGAPORE 45 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6341 1163

EMAIL: NORA.KHALID@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 7690 R

PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER WIRING SET <i>Not in</i>	1	\$ 567.00	+
22	HORN - RH <i>Not in</i>	1	\$ 139.00	+
23	HORN SUPPORT - RH <i>Not in</i>	1	\$ 33.00	+
24	BONNET <i>Dented</i>	1	\$ 3,425.00	✓
25	BONNET ATTACHMENT PARTS <i>Not in</i>	1	\$ 431.00	+
26	BONNET IMPACT PROTECTION - CENTER <i>Not in</i>	1	\$ 31.00	✓
27	BONNET IMPACT PROTECTION - LH / RH <i>Not in</i>	2	\$ 62.00	✓
28	BONNET STRIKER - RH <i>Not in</i>	1	\$ 56.00	+
29	BONNET LOCK <i>Not in</i>	1	\$ 228.00	+
30	BONNET BOWDEN CABLE <i>Not in</i>	1	\$ 64.00	+
31	BONNET RELEASE LEVER <i>Not in</i>	1	\$ 15.00	+
32	BONNET BOWDEN CABLE - CENTER <i>Not in</i>	1	\$ 64.00	+
33	BONNET RELEASE CABLE COVER <i>Not in</i>	1	\$ 11.00	+
34	FRONT WHEEL HOUSING LINER - RH <i>Not in</i>	1	\$ 262.00	+
35	FRONT WHEEL SPOILER <i>Not in</i>	1	\$ 82.00	+
36	FRONT WHEEL SPOILER LOWER - RH <i>Not in</i>	1	\$ 40.00	+
37	HEADLIGHT - RH <i>Not in</i>	1	\$ 7,693.00	✓
38	LIFT CYLINDER - RH <i>Not in</i>	1	\$ 231.00	+
39	LIFT CYLINDER CORRUGATED PIPE <i>Not in</i>	1	\$ 107.00	+
40	LOCK CARRIER <i>Not in</i>	1	\$ 1,127.00	+
SUB TOTAL SPARE PARTS		:	\$ 14,668.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408698

TEL: 6366 2323 FAX: 6941 1183

EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

WARRANTY FOR MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 7690 R LIST FOR DAMAGE ASSESSMENT FOR PLANNED VEHICLE

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	NETT	REMARKS
21	LOCK CARRIER SUPPORT - RH	1	\$ 43.00	✓
22	A/C CONDENSER	1	\$ 683.00	✓
23	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	✓
24	CHARGED AIR COOLER	1	\$ 654.00	✓
25	CHARGED AIR COOLER PRESSURE HOSE	1	\$ 413.00	✓
26	RADIATOR AIR GUIDE OUTER - RH	1	\$ 32.00	?
27	RADIATOR AIR GUIDE INNER - RH	1	\$ 14.00	?
28	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	?
29	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00	?
30	FRONT NO PLATE	S/N	\$ 60.00	✓
31	SUNDRIES		\$ 350.00	?
TOTAL SPARE PARTS		:	\$ 23,611.00	
TOTAL LABOUR CHARGES		:	\$ 8,622.00	
GRAND TOTAL		:	\$ 32,233.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES BODY REPAIR



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NOT FOR ACCIDENT VEHICLE REGN NO: SMH 7590-2 LIST FOR MATERIAL MET FOR MATERIAL USE FOR REGISTERED VEHICLE

NAME: Adrian
 SURVEYED DATE: 16/02/22
 AUTHORISED DATE: 16/02/22
 EXCESS COST: :
 LIABILITY: :
 REMARKS: : Not Authorised, 04 Pags

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT