

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	11 Feb 2022 13:35	Clm Veh Model Changed		[] Merimen Administrator
2	11 Feb 2022 13:35	Clm Created	Reg No: SMP5396L. Policy No: 1900165810-02. Acct Date: 2022/02/10. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R222B0001	[I] Merimen Administrator
3	14 Feb 2022 08:57	Clm Registration Modified	Acct Time:06:44:00->06:00:00. Pol No:1900165810-02->1900165810. Init.Est.:-> 5,000 - 6,000.	[I] Low, Xianyu
4	17 Feb 2022 12:41	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] NA MENG YAN
5	17 Feb 2022 12:41	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] NA MENG YAN
6	17 Feb 2022 12:42	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] NA MENG YAN
7	17 Feb 2022 12:42	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/02/28	[A] NA MENG YAN
8	17 Feb 2022 12:42	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] NA MENG YAN
9	17 Feb 2022 12:42	Clm Registration Modified	Rep:1137->200611.	[A] NA MENG YAN
10	17 Feb 2022 12:42	Clm Veh Model Changed	(206496) AUDI A5 2.0 SB TFSI S TRONIC (DESIGN) (A).	[A] NA MENG YAN
11	17 Feb 2022 12:43	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] NA MENG YAN
12	17 Feb 2022 14:23	Adj Rpt Initiated		[A] HUEY YON
13	17 Feb 2022 14:23	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
14	17 Feb 2022 14:23	Clm Dtl Modified	JPJ Reg. Date: -> 2019/09/30.	[A] HUEY YON
15	17 Feb 2022 14:23	Clm Details Notified		[A] HUEY YON
16	17 Feb 2022 16:14	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/02/28	[A] DENISE TAY KWEE CHENG
17	17 Feb 2022 16:14	Adj Mandate Request	Cur.Reg:11338.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
18	18 Feb 2022 11:16	Clm Registration Modified	Excess: -> 800.00. Excess Waived: -> 800.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Hor, Yinrul
19	18 Feb 2022 13:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/02/28. Mandate Remarks: Vehicle may commence repair. Checked and Supplementary items to resurvey with CLEAR damage photos. Before paint and New parts photos to be documented in Merimen.	[I] Lim, Kok-Chong
20	18 Feb 2022 13:44	Adj Mandate Set	Approved:11338.00:Vehicle may commence repair. Checked and Supplementary items to resurvey with CLEAR damage photos. Before paint and New parts photos to be documented in Merimen.Reinsp:Yes.	[I] Lim, Kok-Chong
21	04 Mar 2022 16:11	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/02/28	[A] SHIAU CHAN

AUDIT TRAIL				
No.	On	Audit	Remarks	By
22	04 Mar 2022 16:12	Adj Mandate Request	Cur.Req:23659.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SOME CHECK ITEMS.	[A] SHIAU CHAN
23	04 Mar 2022 16:36	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/02/28. Mandate Remarks: Checked and Supplementary items to resurvey with CLEAR damage photos. Before paint and New parts photos to be documented in Merimen.	[I] Lim, Kok-Chong
24	04 Mar 2022 16:36	Adj Mandate Set	Approved:22473.00: Checked and Supplementary items to resurvey with CLEAR damage photos. Before paint and New parts photos to be documented in Merimen.	[I] Lim, Kok-Chong

Date From



Date To



Audit Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2766719	17 Feb 2022 14:23:59	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMP5396L		11.00