

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883  
TEL 6747 6106 (6 lines) Fax 6744 2368 Email [service@smemotor.com.sg](mailto:service@smemotor.com.sg)  
GST 201119451E RCB NO 201119451E

TEL: Singapore 193300 FAX:  
ATTN: Motor Claim Department  
Your Ref No : 22/LP/OD-079 (02)  
Claim Type : OD Claim  
Accident Date : 15/02/2022

Reg. No :

1

Delet

the phot. other sep.

## Add 10%

|   |                                                 |                   |      |
|---|-------------------------------------------------|-------------------|------|
| 1 | WIRE CHECKING                                   | \$30.00           | 20   |
| 2 | REMOVE & REFIX FRT WINDSCREEN                   | \$120.00          | 11 X |
| 3 | REMOVE & REFIX DASHBOARD                        | \$250.00          | X    |
| 4 | REMOVE & REFIX FUSE BOX                         | \$120.00          | ?    |
| 5 | REMOVE & REFIX UNDERCARRIAGE (WITH CROSSMEMBER) | \$350.00          | ?    |
| 6 | WHEEL ALIGNMENT                                 | \$100.00          | ✓    |
| 7 | TRANSFER DOOR COMPONENTS                        | \$100.00          | 60   |
| 8 | LABOUR CHARGE                                   | \$1,500.00        | 1100 |
| 9 | SPRAY PAINTING                                  | \$1,300.00        | 1000 |
|   |                                                 | <u>\$3,870.00</u> |      |

|                      |             |
|----------------------|-------------|
| Amount Before Excess | \$31,800.05 |
| Less Excess          | \$0.00      |
| Amount Before GST    | \$31,800.05 |
| Add GST @7%          | \$2,226.00  |
| Total Amount Payable | \$34,026.05 |