

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22001589/Btf3e2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	10/05/2022	
			Code:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJJ 4507H	Veh. Inspected	SML 7443S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10013579/CD	Excess (\$)	0.00	
	Assign From	SHAFWATI MD RABU	Assign Date	18/02/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA NOAH HYBRID 1.8X	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	ZWR800357667	Colour	BROWN	
	Odometer	118824 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	MICHELIN	5 mm	
	L/H Front Tyre	225/45 R17	MICHELIN	5 mm	
	R/H Rear Tyre	225/45 R17	MICHELIN	5 mm	
	L/H Rear Tyre	225/45 R17	MICHELIN	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	24/01/2022	Inspection Date	21/02/2022	
	Survey held at	BIFROST AUTO PTE LTD			
		8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.		Estimate Days of Repair			

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: