



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL	INV No.	AC2201136
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER	INV Date	03/03/2022
SINGAPORE 048623	Reference	CS3/SMO22001601/Uvf3e2
	Code	SMO

PROFESSIONAL SERVICE FEE

Vehicle No.	GBL 4280U
Insured Veh.	GBD 6194P
Claim No.	CMTD2200282/AGC
Policy No.	
Accident Date	19/01/2022
Inspection Date	21/02/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 21.02.2022)	10.00
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 23.02.2022)	10.00
Subtotal	120.00
GST (7%)	8.40
Grand Total	128.40

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM