

Our Job Ref No : 305504066
Date : 11/02/22

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6548 8156

FINALIZATION FORM

To : LKK

Attn : THEVAN

Vehicle Reg No. : SHC3707P

Date of Accident : 05/02/22

Fax :

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SKK2450H

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges (include advertisement stickers etc,if any)

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

\$900.00

\$900.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : THEVAN

Date :

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 7-Feb-22INSURANCE: NTUC (LKS)MODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHC3707P

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Headlamp RH	1		\$1,993.65 XSV
	Frt Bumper	1		\$430.90 / 44
	Frt Bumper Upper Moulding	1		\$368.50 XSV
	Frt Bumper Side Bracket RH	1		\$35.00 / 44
	Frt Bumper Clips	10	\$2.20	\$22.00 / 44
	Daylight RH	1		\$642.50 XSV
	Daylight Grille RH	1		\$93.45 / 44
	SUB TOTAL			\$3,586.00
	LESS 20%			\$717.20
	DISCOUNTED TOTAL			\$2,868.80
	<u>Labour Charge</u>			\$400.00
	Panel Beating			\$600.00
	Spray Painting Charge			\$40.00
	Check Lightings			\$40.00
	Tuff Kote			
	TOTAL LABOUR			\$1,080.00
	ESTIMATE TOTAL			\$3,948.80

Handwritten notes on the right side of the table:
 465.08
 350
 2610 250
 20
 20
 1105
 854
 = 900

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan 82235769

7/42/22 1600

L/S after repair photo
2 days wp

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: