



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042



ESTIMATE COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD		NAME :		WIP : 46032				
36 ROBINSON ROAD		ADDRESS :		EXCESS :				
#16-01 CITY HOUSE				DATE: 17-Feb-22				
SINGAPORE 068877								
ATTN. : MOTOR CLAIMS		TEL :						
FAX :								
VEH NO :	SMP3812R	DATE IN :		CONTACT PERSON :	JESS			
CHASSIS NO :	JM6BP2SAAK1100926	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM			
MODEL :	M3 M-HYBRID	DATE REG:	24-Sep-19	POLICY NO. :				
<u>NATURE OF WORKS</u>								
<u>Parts Description</u>								
NO	DESCRIPTION	QTY	UNIT PRICE	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER	1	997.40			MBCKA-50-221ABB		997.40
2	BRACKET CENTER REAR BUMPER	1	5.40			MDFR5-50-251		5.40
3	REINFORCEMENT REAR BUMPER	1	541.70			MBCJH-50-260		541.70
4	GROMMET,SCREW	4	2.40			MBCKA-50-0Z1		9.60
5	RETAINER RH REAR	1	33.20			MBCKA-50-2H1		33.20
6	COVER TOWING HOOK LH REAR	1	12.80			MBCKA-50-EL1 BB		12.80
7	COVER TOWING HOOK RH REAR	1	12.80			MBCKA-50-EK1 BB		12.80
8	REFLECTOR LH	1	36.00			MB0J8-51-5M0		36.00
9	REFLECTOR RH	1	36.00			MB0J8-51-5L0		36.00
10	GROMMET,SCREW	4	2.70			MBHN1-50-0Z1A		10.80
11	PLATE SET RR BUMPER	1	213.80			MBCKA-50-2C0A		213.80
12	STAY,RR BUMPER	1	91.90			MBCKA-50-290		91.90
13	COVER,UNDER-REAR	1	63.20			MBCKA-50-C51C		63.20
14	FASTENER	4	3.00			MB45A-56-146A		12.00
15	TAPE,PROTECTOR	3	4.70			MBCKA-50-EM1		14.10
16	BRACKET RETAINER S.S ULTRASONIC	2	23.40			MB0J8-67-UC6		46.80
17	RETAINER S.S ULTRASONIC	1	25.10			MBCPT-67-UC5		25.10
18	RETAINER S.S ULTRASONIC	1	25.10			MBCPV-67-UC5		25.10
19	RETAINER S.S ULTRASONIC	1	57.80			MB0J5-67-UC5 2M		57.80
20	RETAINER S.S ULTRASONIC	1	62.20			MB0J6-67-UC5 PR		62.20
21	SENSOR ULTRASONIC REAR	4	190.00			MB0J8-67-UC1 2M		760.00
22	CORD SHORT RR BUMPER	1	474.20			MBCWC-67-A20A		474.20
23	CAMERA-BACK MONITOR	1	1,016.00			MB0L1-67-RC0C		1,016.00
24	LAMP, LICENSE PLATE	1	115.00			MB0J8-51-26Y		115.00
25	TRUNK LID	1	896.00			MBCY0-52-61XA		896.00
26	WEATHERSTRIP TRK LID	1	84.70			MBCJH-56-95XA		84.70
27	FASTENER	11	3.60			MBP4K-58-762		39.60
28	COVER,HOLE RR LID	3	2.50			MD24H-62-866		7.50
29	GASKET LAMP TRUNK LID	2	19.80			MBCJH-51-3H8		39.60
30	FASTENER	2	6.20			MEG21-51-146		12.40
31	GROMMET,SCREW-R.COMB	2	3.30			MGA7B-51-146		6.60
32	ORNAMENT MAZDA 3	1	42.50			MBCJH-51-771A		42.50
33	ORNAMENT SKYACTIV	1	34.60			MBCJH-51-721		34.60
34	EMBLEM RR M-HYBRID	1	36.70			M11-M-HYBRID		36.70

35	0	0	-		0		-
SUPPLEMENTARY							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1							
					TOTAL PARTS		-
					TOTAL PARTS COST		-
Labour Description							
						REVISED	PRICES
1		TO REPLACE REAR BUMPER , TRUNK LID AND REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.					2,640.00
2		TO RESPAY REAR BUMPER , TRUNK LID AND ALL AREAS AFFECTED BY THE ACCIDENTS.					2,520.00
3	MZ-BR-REVERSE	TO TRANSFER REVERSE SENSORS.					660.00
4	MZ-BR-PLATE	TO SUPPLY NUMBER PLATE.				NETT	70.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.					250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.					300.00
7	MZ-BR-SUNDR	SUNDRIES.					50.00
SUPPLEMENTARY LABOUR DESCRIPTION							
1		#N/A					
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.					TOTAL LABOUR	-	-
					TOTAL PARTS	-	-
					TOTAL	-	-
					LESS EXCESS	-	-
					TOTAL AFTER EXCESS	-	
					GST 7%	-	-
					GRAND TOTAL	-	-

TRANS EUROKARS PTE LTD

 Authorised Signature