BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE:

28-Feb-22

INSURANCE: Buyy Dirat

MODEL:

HYUNDAI 140

VEHICLE NO.: SHD 3008T (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
AIR CLEANER ASSY "-	1	\$325.00	\$325.00
AIR DUCT bales	1	\$171.70	\$171.70
FRONT SAFETY BELT ASSY (LH/RH) GOLLAN	2	\$477.20	\$954.40
EXHAUST PIPE CENTRE #†	1	\$ 730.10	\$730.10
SUB TOTAL			\$2,181.20
LESS 20%			\$436.24
DISCOUNTED TOTAL			\$1,744.96
Labour Charge			
Remove/Refix Air Bag/Steering Wheel/Dashboard/Seat	1	\$550.00	\$550.00
Remove/Refix Front Seat Belt	2	\$120.00	
TOTAL LABOUR			\$790.00
ESTIMATE TOTAL			\$2,534.96

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1684.96