

TP Budget Direct.
Veron.

SLG 680H. 2016 Sept

Nissan Note 1198cc

JN1TBAF12Z0982524

Rear Number Plate	2 x 30(SN) ✓
Rear Number Plate Holder	30(SN) ✓
Rear Bumper Dehd	465.80 ✓
Rear Bumper Clips. n/m	30(SN) ✓
Rear Bumper Side Holder x 02 LH	47.10 $47.1 \times 2 = 94.20$
Rear Bumper Impact Bracket x 02 LH	86.60 $86.6 \times 2 = 173.20$
Rear Bumper Sponge. A/L d	128.60 ✓
Reverse Sensor Damged	280(SN) 200(SN)
Rear End Panel Dented	586.90 ✓
Rear End Panel Top Garnish dehd	85.90 ✓
Rear End Panel Top Garnish Clips. n	20(SN) ✓
Rear End Panel Sealant. n/a	60(SN) ✓
Taillamp x 02 A/L A/L d	435.40 343.10 $435.4 \times 2 = 870.80$
Tailgate Distorted	998.90 ✓
Tailgate Lock Damged	149.80 ✓

4004.10

SLG680H.

Tailgate Weatherstripe.	Cut	126.20	✓
Tailgate Inner Trim Board	torn	245.20	✓
Tailgate Inner Trim Board clips. m		30(SN)	✓
Tailgate Glass Sealant.		60(SN)	✓
Nissan Logo	New	65.70	✓
Wipe Wording		80.20	✓
DIG-S Emblem.		60.40	✓
Spere Tyre Panel Top Board	torn	298.40.	✓
Reer Fender Inner Trim Board	x 02 ^{LA} cut	298.9 x 2 = 597.80	298.90
Reer Fender Inner Trim Board clips. m		60(SN) 30(SN)	
		1623.90	
	4067.70	S.N: 430	
	3660.93		

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

SLG 680H.

Panel Beating

~~1200~~ 800

Spray Painting

~~1200~~ 800

Wiring

~~50~~ 30

To remove reverse sensor

~~40~~ 50

To remove upholstery

~~150~~ 60

To spray tuff coat

~~150~~ 60

To transfer tailgate fittings.

~~150~~ 80

To remove tailgate g/s

~~180~~ 120

3180

8808.00

total: 6090.93

L/S 4850

06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: