

See File By:

Thawn

Ref:

NHuc

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 6716Z

Yr Rogn:

24/4/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Viano

c.c 2143

Colour

White

A/C: Insured / Std / Nil / NA

Sp. Reading

761163

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

WDF 63981323858601

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 3 Rim / STD A/Rim or

Tyre Size:

F:

195/65R16

R:

195/65R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

7/2/22

D.O.I.

7/2/22 16/5

Survey held at

CDGE

Des. of Damages: Front / Rear / O/S / N/S / UIC / Roof/Top or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO GIA GIVEN

recommended total ~~loss~~ lost

not economical to repair

Book Value: 31292

rebate: 32869

Date/Time, File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS = \$

Fuel/Bus

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: VV&I and (\$

Request Form:

Date: 24/4/14

REPAIR ESTIMATE

Date: 07/02/2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$1,372.00
	REAR BUMPER SIDE LH RR			\$473.60
	REAR BUMPER SIDE RH RR			\$473.60
1	REAR BUMPER REINFORCEMENT			\$462.48
	REAR BUMPER REFLECTOR LH			\$46.00
	BUMPER PROTECTOR			\$205.18
	CROSSMEMBER STAY RR			\$141.14
	TAIL GATE TRIM COVER			\$320.00
	TAIL GATE WHEATHERSTRIP			\$166.63
	TAILGATE MERCEDES STAR LOGO			\$45.46
	TAIL GATE 2.2 LOGO			\$78.00
	TAIL GATE CDI LOGO			\$78.00
	TAIL GATE VIANO LOGO			\$78.00
	TAIL GATE LOCK			\$273.40
	TAIL GATE LOCK OUTER HANDLE			\$175.54
	TAIL GATE STEP GARNISH			\$161.45
	TAIL LAMP ASSY LH			\$622.44
	TAIL LAMP ASSY RH			\$622.44
	TAIL LAMP LOWER GARNISH LH			\$61.90
	TAIL LAMP LOWER GARNISH RH			\$61.90
	REAR PANEL			\$1,208.00
	REAR PANEL GARNISH			\$214.00
	FRT BUMPER			\$1,920.00
	FRT BUMPER BRACKET LH RH		\$66.00	\$132.00
	NUMBER PLATE TRIM COVER			\$193.50
	FRT BUMPER CENTRE GRILLE			\$540.00
	RADIATOR GRILLE.			\$1,960.00
	FRT BUMPER REINFORCEMENT			\$1,480.00
	SUB TOTAL			\$13,566.66
	LESS 20%			\$2,713.33
	DISCOUNTED TOTAL			\$10,853.33
	FRT NUMBER PLATE			\$50.00
	TAIL GATE MAXICAB LOGO			\$30.00
	REAR BUMPER REVERSE SENSOR			\$288.00
				\$368.00
	Labour Charge			
	PANEL BEATING			\$2,000.00
	SPRAY PAINTING CHARGE			\$1,000.00
	TUFF KOTE			\$50.00

Qty	Parts Description / Labour	Type	Unit Price	Amount
	REMOVE/REFIX REVERSE SENSOR			\$120.00
	CHECK ALL LIGHTING			\$80.00
	TOTAL LABOUR			\$3,250.00
	ESTIMATE TOTAL			\$14,471.33
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Thuvun

82235769

7/2/22 16/5

L/S after repair photo

5 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHB6716Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Feb 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	VIANO 2.2 CDI TREND LONG
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	65194031979326
Chassis No.:	WDF63981323858601
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$42,965.00
Original Registration Date:	24 Apr 2014
First Registration Date:	24 Apr 2014
Transfer Count:	0
Actual ARF Paid:	\$52,151.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Apr 2022
PARF Rebate Amount:	\$31,290.00
Intended COE Rebate Details	
COE Expiry Date:	23 Apr 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$59,871.00
COE Rebate Amount:	\$1,579.00
Total Rebate Amount:	\$32,869.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Feb 2022

OK

Date/Time: 07.02.2022 12:39

Page : 1

JOB CARD Sales Order: 4170538

JC NO 305504009

am: ARC Repair TP(CLSO)1

OMER
S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

REGN NO.: SHB6716Z	MILEAGE
MAKE: MERCEDES BENZ	FUEL E.....1/2.....F
MODEL VIANO CDI 2.2L	DATE/TIME IN 07.02.2022 09:40
YR OF MANU. 24.04.2014	TARGET DATE
CHASSIS CODE WDF63981323858601	COMPLETION DATE/TIME:


JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 07.02.2022
ATURE: 3P 07.02.22

'NO LABOR CODE

DESCRIPTION



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Io.: **SHB6716Z** **YY**

Vehicle No.: **SHB6716Z**

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

Vehicle NBV for Fleet Safety Division

Report ID : 2817122
 DATE : 07/02/2022
 TIME : 14:00:01

Confidential Transportation 22
 Vehicle NBV for Fleet Safety Division
 AS AT 31.01.2022

Page 12 of 100
 Page 12

Co.Code : CTPL
 License Plate : SHB6716Z
 Old Asset No :
 Veh.Model : Mercedes Viano 7 seater Maxicab
 Reg.Date : 24.04.2014
 Cap.Date : 24.04.2014
 Accident.Date : 07.02.2022
 Veh.Age : 094

Asset No	SN.No	Bal.Dep.Mths	Per.Mth.Dep	Bal.Dep.Value	Asset Description 1	Cost	Op.Acc.Dep	Cur.Year Dep	Accum. Dep	Net Book Value	Scrap value/Estimated 2022 Refund
10031207	0	000	700.60	0.00	SHB6716Z MWN 24.04.2014 BASIC COST W AIRCON	63,053.67	63,053.67-	0.00	63,053.67-	1.00	1.00
10031207	1	000	95.48	0.00	SHB6716Z MWN 24.04.2014 IMPORT DUTY 2010WV42965	8,593.00	8,593.00-	0.00	8,593.00-	0.00	0.00
10031207	2	000	231.78	0.00	SHB6716Z MWN 24.04.2014 ARF XMONV642965	52,151.00	20,860.00-	0.00	20,860.00-	31,291.00	31,291.00
10031207	3	000	665.23	0.00	SHB6716Z MWN 24.04.2014 COE 80%	59,871.00	59,871.00-	0.00	59,871.00-	0.00	0.00
10031207	4	000	0.00	0.00	SHB6716Z MWN 24.04.2014 COE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
10031207	5	000	0.00	0.00	SHB6716Z MWN 24.04.2014 AIR CONDITIONER	0.00	0.00	0.00	0.00	0.00	0.00
10031207	6	000	0.00	0.00	SHB6716Z MWN 24.04.2014 PRINTER DIGITEX THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
10031207	7	000	0.00	0.00	SHB6716Z MWN 24.04.2014 TAXIMETER DIGITEX FI	0.00	0.00	0.00	0.00	0.00	0.00
10031207	8	000	1.56	0.00	SHB6716Z MWN 24.04.2014 VEH REG FEE	140.00	140.00-	0.00	140.00-	0.00	0.00
			1,694.65	0.00		183,809.67	152,517.67-	0.00	152,517.67-	31,292.00	

COE
 Vehicle

Vehicle : Without T/M & COE
 Vehicle : Without T/M, With COE
 Taximeter

92,646.67-
 152,517.67-
 0.00

31,292.00
 31,292.00
 2.00