

Our Job Ref No : 305504085						ENGINEERING				
Date : 11/02/22						ComfortDelGro Engineering Pte Ltd 59 Loyang Drivo Singapore 508969 Fax: 6546 8156				
FINA	LIZATI	ON FORM								
То	:		LKK		-	Fax:				
Attn	: Mr		Thevan		mana.					
Vehicle Reg No. SHB4682A				CCPL		-	07/0/2022			
The s	survey a	and estimates of the	ne repairs of the a	bove-mentio	ned vehicle a	are as follows:	-			
1.	The repair job shall bill to:			NTUC		***	XE1119A			
2.	The fi	nalized amount st	nall be:							
	(a)	Spare Parts after	r List discount				place grown and approximately regard to the control of the control			
	(b) Labour Charges									
		Total for Part-B	y-Part Repair Co	st			\$0.00			
	(c.)	Lumpsum Repai								
	(0.)	Total for Lumpsu	m repair cost afte	r Less:	20%		¢2.050.00			
		Final Lumpsum	Repair cost				\$2,950.00			
3.	Estimated normal period for repairs: 4 working days.									
 We shall treat the above amount as Correct and Confirmed if there is no reply from you within working days 										
5.	Thank	k you for your ass	istance	We	We confirm the estimates and					
J.	mani	t you for your ass	istarioo.	0	fina					
	Signature :			X			\mathcal{O}_{l}			
				1	Cia	nature:	U/h			
					Sig Na		Thevan			
	Name : <u>Ms Loke YY</u> Tel : 62148355				Da		Theren			
	Tel									
	Fax	6546815	0							
For C	Official	Use Only			-					
	Item		Amoun		Document Attached Yes or No	Confirm By (Signature)	Remarks			
1 R	Rental Rate P/Day				YES					
		ncome Paid			NO					
3. Survey Fees			,		· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·				
4. LTA Search Fee		\$7.49 / \$2	2.00			L				
Medical Fees (on behalf of driver, if applicable)										
	verrun									
Rema	arks:									

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB4682A

Make

: HYUNDAI

Model : 1-40 Date: 07/02/22

Insurance: NTUC -

MVA: MS, LOKE YY

aty	Parts Description / Labour	Туре	Unit Price	Amount
	1 RR FENDER RH			\$2,171.40
	1 REAR BUMPER			\$553.00
1	ORR BUMPER CLIPS			\$22.00
	1 RR WHEEL HUB CAP RH			\$214.20
	1 TAIL LAMP RH			\$697.80
	SUB TOTAL			\$3,658.40
	LESS 20%			\$731.68
	DISCOUNTED TOTAL			\$2,926.72
	REAR BUMPER METAL MAT			\$50.00
				\$50.00
	Labour Charge			
	PANEL BEATING			\$1,200.00
	SPRAY PAINTING CHARGE			\$600.00
	REMOVE/ REFIX UPHOLSTERY & CUSHION RR		2	\$120.00
	TUFF KOTE			\$60.00
	CEHCK ALL LIGTHING			\$60.00
	TOTAL LABOUR			\$2,040.00
	ESTIMATE TOTAL			\$5,016.72

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theran 82235769

7/2/22 1800 L/S AFF postat orafle repair phone Text Udays wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- · To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

" nte:

Page 1