

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
N	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI22001696/Kvf3e2	
	36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date:	25/02/2022	
			Code:	FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
I	Insured Veh.	XD 3919A	Veh. Inspected	SHD 679B	
F	Policy No.		Coverage (\$)	0.00	
	Claim No.	D22000505MCVT	Excess (\$)	0.00	
/	Assign From	AINI BINTE	Assign Date	22/02/2022	
2. Vehicle Particulars & Condition					
	Make & Model	RENAULT LATITUDE (A)	c.c	1995	
E	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	VF1ABL15AUC283305	Colour	METALLIC WHITE / RED	
	Odometer	404711 KM	Steering	IN ORDER	
E	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
F	R/H Front Tyre	215/60 R16	SAILUN	8 mm	
L	L/H Front Tyre	215/60 R16	SAILUN	8 mm	
F	R/H Rear Tyre	215/60 R16	SAILUN	8 mm	
L	L/H Rear Tyre	215/60 R16	SAILUN	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
/	Accident Date	21/02/2022	Inspection Date	22/02/2022	
	Survey held at	TRANS-CAB AUTO SERVICES I	PTE LTD		
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.	. Remarks				
E	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				