

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

8 SH	A INSURANCE F	PTF LTD			
			Ref:	CS/ASM22001701/Eqy3e2	
,,,,,	HENTON WAY # A TOWERSING#		Date:	23/03/2022	
ATT	N: CHAN KIAN	CHUAN	Code:	ASM	
1. Policy Particulars :- THIRD PARTY CLAIM					
Insu	ured Veh.	SHC 8668K	Veh. Inspected	SMZ 7457D	
Poli	icy No.	VFX/P2419138	Coverage (\$)	0.00	
Clai	im No.	S2M03TTN	Excess (\$)	0.00	
Ass	sign From	CHAN KIAN CHUAN	Assign Date	22/02/2022	
2. Vehicle Particulars & Condition					
Mak	ke & Model	B.M.W. 528I	c.c	1997	
Eng	gine No.	HIDDEN	Year of Reg.	2015	
Cha	assis No.	WBA5A52010D823619	Colour	BLUE	
Odd	ometer	97341 KM	Steering	IN ORDER	
Bra	kes	IN ORDER	Modification	SPORTS RIM	
Ger	neral	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
R/H	Front Tyre	245/45 R18	MICHELIN	5 mm	
L/H	Front Tyre	245/45 R18	MICHELIN	5 mm	
R/H	Rear Tyre	245/45 R18	MICHELIN	5 mm	
	Rear Tyre	245/45 R18	MICHELIN	5 mm	
4. Description of Damages					
THE	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAN	DAMAGES SEE DETAILS.				
5. General Information					
Acc	cident Date	16/02/2022	Inspection Date	22/02/2022	
Sur	Survey held at KOK WANG CAR GROOMING (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE SINGAPORE 627605				
5a.					
A)TH B)IN	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
EST	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				