

1 of 2 ?

100%

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (S) PTE LTD

4 SHENTON WAY #21-01

SGX CENTRE 2 SINGAPORE 068807

Ref: CS/MSG22001703/Bvf3

Date: 22/02/2022

Code: MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 3223R	Veh. Inspected	SKK 108K
Policy No.	29091679QMY	Coverage (\$)	0.00
Claim No.	640007	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY MEI LING)	Assign Date	22/02/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/01/2022	Inspection Date	23/02/2022
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

https://views.init.com.sg/report/reportserver?Report=LKKInspection&From=345388&rs:Command=Render&rc:Parameters=false&rc:Zoom=Page ...

1/1