



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM22001718/Bea3q2 Date: 20/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SNA 9991J	Veh. Inspected	SMG 7221S	
Policy No.	P2429987	Coverage (\$)	0.00	
Claim No.	S2M03TOA	Excess (\$)	0.00	
Assign From		Assign Date	22/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. DRIVE 18I	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WBAJG12000EN48941	Colour	GREY	
Odometer	53201 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	PIRELLI	5 mm	
L/H Front Tyre	225/55 R17	PIRELLI	5 mm	
R/H Rear Tyre	225/55 R17	PIRELLI	5 mm	
L/H Rear Tyre	225/55 R17	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS				
5. General Information				
Accident Date	12/02/2022	Inspection Date	22/02/2022	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	