

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SMG 7221 S**

Model : **BMW X1**

Year : **2018**

Chassis No : **WBAJG12000EN48941**

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear bumper	1	\$ 1,608.40	\$ 1,191.60	DDV
2	Rear bumper lower	1	\$ 768.85	\$ 368.85	WTV
3	Rear bumper diffuser	1	\$ 618.00	\$ 318.00	WTV
4	Rear bumper reflector	2	\$ 184.00	\$ 368.00	
5	Rear bumper inner sponge	1	\$ 385.55	\$ 385.55	
6	Rear bumper reinforcement	1	\$ 683.40	\$ 683.40	NDX
7	Rear bumper centre beam	1	\$ 205.80	\$ 205.80	
8	Rear bumper side retainer	2	\$ 61.35	\$ 122.70	NECV
9	Rear bumper bracket	2	\$ 162.65	\$ 325.30	NSX
10	Rear bumper reverse sensor	4	\$ 238.20	\$ 200.00	SCV
11	Rear bumper antenna sensor	1	\$ 418.60	\$ 418.60	
12	Rear end panel	1	\$ 1,051.00	\$ 1,051.00	NDX
13	Rear end panel top garnish	1	\$ 484.30	\$ 484.30	
Parts Sub Total :				\$ 2,201.15	8,232.80
5% Discount :				\$ 110.06	411.64
PARTS TOTAL :				\$ 7,821.16	

2091.09

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Rear bumper clips	1	\$ 60.00	\$ 30.00	NECV
3	Rear bumper lower clips	1	\$ 60.00	\$ 60.00	
4	Rear bumper diffuser clips	1	\$ 60.00	\$ 60.00	NNX
5	Rear bumper reverse sensor seal	4	\$ 25.75	\$ 103.00	NECV
6	Rear end panel sealant	1	\$ 100.00	\$ 100.00	
7	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00	NNX
8	Rear number plate w/casing	1	\$ 80.00	\$ 80.00	
SPECIAL NETT TOTAL :				\$ 730.00	

133.00

Nos.	LABOUR	S\$	
1	R&R rear bumper reverse sensor	\$ 60.00	150.00
2	Check wiring	\$	120.00
3	Diagnostic reset fault code	\$	300.00
4	Upholstery	\$	300.00
5	Panel beating	\$ 200.00	1,000.00
6	Rust proofing	\$	200.00
7	Spray painting	\$ 200.00	1,000.00
LABOUR TOTAL :		\$	3,070.00

Survey
22/2/2022

1640 hrs

Tatim
Mr

Resurvey

23/2/2022

1305 hrs

Tatim
Mr

LABOUR TOTAL : \$ 3,070.00
460.00

PARTS TOTAL : \$ 7,821.16

SPECIAL NETT TOTAL : \$ 730.00

LABOUR TOTAL : \$ 3,070.00

GRAND TOTAL : \$ 11,621.16

Lump sum repair
Repair days 3

Parts 2091.09

SN 133.00

Labour 460.00

2684.09

536.82

2147.27

@ 2070

LS 2150/2

Tatim Mr
27/2/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: