



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2201135

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 03/03/2022
Reference CS3/III22001733/Rtf3e2
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SJM 3663E

Insured Veh. SLU 1870X

Claim No.

Policy No.

Accident Date 19/02/2022

Inspection Date 23/02/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 23.02.2022 04.23pm	
- Dismantle Inspection 24.02.2022 04.19pm	
- After Repair Inspection 28.02.2022 12.45pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM