



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22001740/Kvf3e2	
			Date: 22/03/2022	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLE 6781X	Veh. Inspected	SMC 7360U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D22000533MFZH	Excess (\$)	0.00	
Assign From	VICALPEH	Assign Date	23/02/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA CARENS (A)	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KNAHU815VJ7211225	Colour	METALLIC DARK GREY	
Odometer	318478 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55Z R16	WANLI	8 mm	
L/H Front Tyre	205/55Z R16	WANLI	8 mm	
R/H Rear Tyre	205/55Z R16	DURATURN	8 mm	
L/H Rear Tyre	205/55Z R16	DURATURN	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/02/2022	Inspection Date	28/02/2022	
Survey held at	MUNICH AUTOCARE PTE LTD 60 JALAN LAM HUAT #07-43 CARROS CENTER SINGAPORE 737869			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	