



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS/FCI22001746/Uqf3e2 Date: 28/03/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 1307Z	Veh. Inspected	XD 4207P
Policy No.		Coverage (\$)	0.00
Claim No.	D22000536MFVS	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	23/02/2022
2. Vehicle Particulars & Condition			
Make & Model	mitsubishi FV51JP4RDEA (M)	c.c	12882
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	FV51JPA00607	Colour	WHITE
Odometer	302378 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	FIRENZA	7 mm
L/H Front Tyre	295/80 R22.5	FIRENZA	7 mm
R/H Rear Tyre	295/80 R22.5 (D/D)	FIRENZA	7/7/7/7 mm
L/H Rear Tyre	295/80 R22.5 (D/D)	FIRENZA	7/7/7/7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/02/2022	Inspection Date	24/02/2022
Survey held at	15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01-53		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	