

# Car In

BMW Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401555W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796001 (AfterSales)  
64796024 (Motorrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : **b1 60986** Page No. : **1 of 6**  
Date Estimated : **22/02/2022**  
Prepared By : **Inthiran A/L Thurasamy**

**- ESTIMATE REPAIR FOR -**

Dawn Lim Sock Kiang  
6 Sinaran Drive

Singapore 307468

**- ACCOUNT - 135**

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM955Y	WBACR62040LS15802	24/06/2019	X5 xDrive40i	43253

**DESCRIPTION****VALUE**

To replace front bumper, bonnet, front air duct and to make good left front fender *if full bumper replaced - 4 days*

34X 850

3400 ~~2550~~

4,250.00

To respray front bumper, bonnet and left front fender *2 M*

2197

3,516.00

To carry out body cavity preservation.  
(Per panel).

112

118.00

To replace low temperature cooler assembly including conduct pressure test, bleed cooling system and conduct check for leak.

3

1,062.00

To replace left headlight.

457

481.00

To replace right headlight.

X 2

481.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168

177.00

To check electrical wiring system at the front section for proper function including adjustment of headlights.

168

177.00

To supply front emboss number plate. *CUT*

83.00

Sundries.

nec

150.00

Total Labour 1: **10,495.00****DESCRIPTION****QTY****PRIC****VALUE**BLIND RIVET *7*

12

1.20

14.40

RADIATOR *1*

1

1,090.80

1,090.80

COVER, TOP *1*

1

50.35

50.35

Rock guard *1*

1

100.30

100.30

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438160  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 60986  
Date Estimated : 22/02/2022  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM955Y	WBACR62040LS15802	24/06/2019	X5 xDrive40i	43253

DESCRIPTION	QTY	PRIC	VALUE
HOOD	1	2,240.95	2,240.95
FRT SUPPORT	1	867.75	867.75
FRT BUMPER BOTTOM CARRIER	1	477.30	477.30
LH VERTICAL CONNECTION	1	27.70	27.70
RH VERTICAL CONNECTION	1	27.70	27.70
SUPPORT	2	33.95	67.90
LH BUMPER GUIDE	1	59.10	59.10
LH PEDESTRAIN PROTECTION BRACKET	1	10.80	10.80
RH PEDESTRAIN PROTECTION BRACKET	1	11.95	11.95
GRILLE AIR INLET MIDDLE (M)	1	97.50	97.50
LH GRILLE SIDE OPEN (M)	1	111.05	111.05
RH GRILLE SIDE OPEN (M)	1	111.05	111.05
IMPACT ABSORBER TOP (M)	1	91.30	91.30
LH COVER FOR AIR INLET (M)	1	79.55	79.55
RH COVER FOR AIR INLET (M)	1	79.55	79.55
FRT NUMBER PLATE CARRIER (M)	1	73.40	73.40
LH FOG LAMP SUPPORT (M)	1	72.80	72.80
RH FLAP TOWING LUG PAINTED (SCHWARZ)	1	82.20	82.20
LH AIR INLET FINISHER (M)	1	124.05	124.05
RH AIR INLET FINISHER (M)	1	124.05	124.05
LH AIR CURTAIN (M)	1	52.05	52.05
LH FLAP TOWING LUG PAINTED (SCHWARZ)	1	82.20	82.20
FRT LH SHOCK ABSORBER (M)	1	54.80	54.80
FRT RH SHOCK ABSORBER (M)	1	54.80	54.80
FRT BUMPER PANEL PRIMED (M)	1	1,943.05	1,943.05
FRT BUMPER TRIM PAINTED	1	315.15	315.15
LH FOG LAMP COVER (M)	1	133.60	133.60
RH FOG LAMP COVER (M)	1	133.60	133.60
PLUG	7	1.45	10.15
FRT GRILLE	1	343.95	343.95
EMBLEM GROMMET	2	0.95	1.90
PLAQUE 82MM	1	72.85	72.85
EMBLEM M	1	47.35	47.35
AIR DUCT BOTTOM	1	114.55	114.55
FRT TOP CONNECTION	1	213.05	213.05
FRT CROSSLINK	1	232.40	232.40
FRT LH SUPPORT PANEL	1	70.30	70.30
FRT RH SUPPORT PANEL	1	70.30	70.30
AIR DUCT RADIATOR TOP	1	68.35	68.35
AIR DUCT RADIATOR BOTTOM	1	68.35	68.35
FRT LH BRAKE AIR DUCT	1	52.05	52.05
LH WHEEL ARCH AIR DUCT BRAKE	1	52.05	52.05
AIR FLAPS TOP (M)	1	315.95	315.95
LH HEADLIGHT LED TECHNOLOGY	1	4,727.25	4,727.25
RH HEADLIGHT LED TECHNOLOGY	1	4,727.25	4,727.25
LH FOG LIGHT LED	1	483.70	483.70
LABEL COOLANT 650+/-15G	1	24.65	24.65
(S/L) ANTI FREEZE 1.5 LITRES	3	20.70	62.10



# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 60986 Page No. : 3 of 6  
Date Estimated : 22/02/2022  
Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM955Y	WBACR62040LS15802	24/06/2019	X5 xDrive40i	43253

Total Parts : 20,621.25

Steve (LKK)  
23/2/22, 4.3pm

mm PL  
P/P  
By BL L  
9 0 - 1/2 L



Labour 1	:	10,495.00
Parts	:	20,621.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,178.14
Grand Total	:	33,294.39

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*