

Repair Estimate

Not Nuthorn

8.2727.72

Rearry

12 By

4 REPAIR DAYS

Thiam Heng Huat Pte Ltd 176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA CITY Engine/Chassis No.: MRHGM6660KT000569 Date of accident: Damaged area: N/S Front

Date: 25/02/2022 Claim Type: TP VRN: SMJ1894Z



-	items	A STATE OF THE STA			166			THE WA
5/1	, are acscription	Marion	T	QTY	U	NIT PRICE		AMOUNT
1	Front foglamp garnish n/s	Se	n	1	\$	48.30	5	48.30
2	Front fender n/s 453-80	6	'n	1	\$	518.00	\$	518.00
3	Front fender inner cowling n/s	A Company	2	1	\$	132.50	\$	132.50
4	Front Bumper	Alle land	a.	1	\$	559.00	\$	559.00
5	Front Bumper side retainer	ALC: U	17	2	\$	45.00	\$	90.00
6	Front Bumper impact absorber		h	1	\$	112.00	\$	112.00
7	Front Bumper reinforcement	,	n	1	5	350.00	\$	
8	Radiator grille 162.70	Mic	20	1	5	387.00	\$	350.00
9	Radiator grille "HONDA" emblem 58.40	In.	<u>m</u>	1	\$		-	387.00
	Radiator grille chrome garnish upper	•	7		-	160.00	\$	160.00
	Radiator grille chrome garnish lower	In		1	\$	180.60	\$	180.60
200	Radiator grille base	JL		1	\$	245.00	\$	245.00
_	leadlamp lower bracket n/s	PL	2	1	\$	198.00	\$	198.00
	eadlamp n/s	0	m	1	\$	69.00	\$	69.00
+		me	W	1	\$	849.30	\$	849.30
IF	ront foglamp n/s	^	1	1	\$	305.90	\$	305.90
_					Subtotal	\$	4,204.60	
					st discount		20.00%	
			4.0		M.	Total	\$	3,363.68

No.	Parts description		QTY	UNIT PRICE		AMOUNT	
1	Sundries	NA	1	\$	50.00		50.00
2	Front Bumper clips	Na	10	\$	4.50	\$	45.00
3	Front support top panel garnish clips	~~	4	\$	4.50	\$	18.00
4	Front fender inner cowling n/s clips	NA	8	\$	4.50		36.00
5	Front licence plate & frame	In	1	\$	55.00	\$	55.00
	To					\$	204.00

ONC AUTOMOTIVE

Repair Estimate

Labour							
No.	Description	Work unit		Amount			
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$	1,000.00			
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.5	\$	100.00			
3	Supply spray paint material and necessary items to respray affected area / panel.	5	\$	1,000.00			
4	To rust proof all affected portions after repair.	0.5	\$	100.00			
	A POST AND ADDRESS OF COMMENT AND ADDRESS OF A STATE OF COMMENT AND ADDRESS OF A STATE O	otal labour	\$	2,200.00			

5,767.68 Estimate Grand Total \$

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: