

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 18 Mar 2022

Preliminary Advice

Vehicle No	: SMY9247K	Accident Date	: 19/02/2022
Make	: AUDI A6	Policy No.	: 7210032966
Assignment Date	: 24/02/2022	Excess	: S\$800.00
Date of Inspection	: 23/02/2022	Est. Duration of Repair	: 25
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 156,391.00
Revised Amount	:S\$ 108,930.00
Check Items (Estimated)	:S\$ 15,502.00
Total	:S\$ 124,432.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$ 285,713.00
Pre-Accident Value	:S\$ 215,000.00
COE / PARF Rebate	:S\$ 79,819.00
Salvage Value	:S\$

Margin for Repair (New for Old Value) :S\$ 205,894.00

Margin for Repair (Pre-Accident Value) :S\$ 135,181.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.