

⏪

⏩

1

of 2 ?

⏪

⏩

↺

↻

100%

⏴

⏵

Find

Next

LKK

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Ref: CS/FCI22001803/Kqf3

Date: 24/02/2022

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.

GBC 1990X

Veh. Inspected

SMQ 3356K

Policy No.

Coverage (\$)

0.00

Claim No.

D22000512MFCV

Excess (\$)

0.00

Assign From

AINI BINTE

Assign Date

24/02/2022

2. Vehicle Particulars & Condition

Make & Model

c.c

0

Engine No.

HIDDEN

Year of Reg.

Chassis No.

Colour

Odometer

-

Steering

Brakes

Modification

General

3. Conditions of Tyres

Size

Make

Balance

R/H Front Tyre

mm

L/H Front Tyre

mm

R/H Rear Tyre

mm

L/H Rear Tyre

mm

4. Description of Damages

5. General Information

Accident Date

20/02/2022

Inspection Date

25/02/2022

Survey held at

10 Ang Mo Kio Industrial Park 2A #01-05

Repairer

OPTIMA WERKZ PTE LTD

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.