

SERVICE ESTIMATE

88013 - C00001
Mr Chua Eng Sway
17 Faber Walk

Singapore
Singapore 128959

Closed by : Joseph Tan
Svc Consultant :
Remarks : Mr Chua Eng Sway

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

0 Page 1

Inv.No. . : B&P
Inv.date. : 02/03/2022
WIP No. . : 13711
Veh.In/Out: 12/02/2022
*Tel.No. . : Mobile: 83399180
Reg.No. . : SLJ9065J
Reg.date . : 29/12/2016
Mileage .. : 0
Chassis No: YV1FS28C0H2432056

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR BUMPER, REAR LOWER SPOILER, ETC	0	2550.00	0	850	2,550.00	S
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR LOWER SPOILER, ETC	0	3000.00	0	750	3,000.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELETRICAL MODULES	0	540.00	0		540.00	S
	BUMPER COVER REAR S6	1.0 EA	2087.70			2,087.70	S
	TOW COVER REAR S60 1	1.0 EA	89.80			89.80	S
	BUMPER SPOILER REAR	1.0 EA	590.40			590.40	S
	PROTECTING PLATE REA	1.0 EA	538.40			538.40	S
	BUMPER BRACKET CTR R	1.0 EA	167.10			167.10	S
	BUMPER BRACKET REAR	1.0 EA	66.10			66.10	S
	BUMPER BRACKET REAR	1.0 EA	66.10			66.10	S
	BUMPER BRACKET REAR	1.0 EA	44.60			44.60	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

0 L V O



SERVICE ESTIMATE

88013 - C00001
Mr Chua Eng Sway
17 Faber Walk

Singapore
Singapore 128959

Closed by : Joseph Tan
Svc Consultant :
Remarks : Mr Chua Eng Sway

SL: SERVICE SALES - PC

GST Reg.No:M28920628X
0 Page 2

Inv.No. . : B&P
Inv.date. : 02/03/2022
WIP No. . : 13711
Veh.In/Out: 12/02/2022
*Tel.No. . : Mobile: 83399180
Reg.No. . : SLJ9065J
Reg.date . : 29/12/2016
Mileage ... : 0
Chassis No: YV1FS28COH2432056

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET RHR S	1.0 EA	66.10			66.10	S
	BUMPER INSTALLING MT	1.0 EA	101.40			101.40	S
	BUMPER CLIP 8x8,5	10.0 EA	8.20			82.00	S
	CLIP XC90 16- XC60	10.0 EA	8.80			88.00	S
	EMBLEM 'VOLVO' REAR X	1.0 EA	121.80			121.80	S
	EMBLEM 'S60' CH 1700 X	1.0 EA	112.30			112.30	S
	EMBLEM 'T2' S60 16- X	1.0 EA	112.30			112.30	S
	PARKING SENSOR 29dB	4.0 EA	235.60			942.40	S
	CABLE HARNESS REAR B	1.0 EA	133.80			133.80	S

Steve (LKK)
2/3/22, 10.30a

WZ 1C
PIP
by Buly
3 djs

Labour Total 6,090.00
Parts Total 5,410.30
Package Total 0.00

Gross Total. 11,500.30
Net..... 11,500.30
GST @ 7.0% 805.02
Total..... 12,305.30
Paid..... 0.00
Please Pay.. 12,305.30

GST: S=StdRated; O=OutOfScope; Z=ZeroRated