



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

PORSCHE

LONPAC INSURANCE BHD		NAME :		WIP : 27739	
300 Beach Road, #17-04/07		ADDRESS :		EXCESS :	
The Concourse				DATE: 24-Feb-22	
Singapore 199555					
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					

VEH NO :	SMX6204J	DATE IN :		CONTACT PERSON :		JOB :	63310682
CHASSIS NO :	WP0ZZZ98Z7U722153	MILEAGE :		TYPE OF CLAIM :		THIRD PARTY	
MODEL :	987 Boxster S Tiptronic	DATE REG.:	12-Jun-07	POLICY NO. :			

NATURE OF WORKS

S/NO	Parts Description	QTY	1ST	SUPP	REVISED	PRICES
1	FRONT BUMPER <i>de /</i>	1				\$ 1,770.10
2	TOWING COVER <i>X</i>	1				\$ 38.30
3	GRILLE FRAME LH <i>X</i>	1				\$ 359.10
4	GRILLE FRAME RH <i>X</i>	1				\$ 359.10
5	BUMPER REINFORCEMENT <i>?</i>	1				\$ 386.00
6	IMPACT ABSORBER-FRT <i>?</i>	2				\$ 530.80
7	SEAL-IMPACT ABSORBER FRT <i>?</i>	2				\$ 17.60
8	FRONT BUMPER CENTER BRACKET <i>?</i>	1				\$ 113.40
9	RETAINER LH <i>X</i>	1				\$ 33.50
10	RETAINER RH <i>X</i>	1				\$ 33.50
11	FRONT BUMPER CENTER TRIM <i>X</i>	1				\$ 252.70
12	FRONTBUMPER CENTER TRIM BRACKET <i>X</i>	1				\$ 232.10
13	LICENSE PLATE BRACKET <i>mu /</i>	1				\$ 43.50
14	PROTECTIVE FILM-LH (NEC) <i>mu /</i>	1				\$ 20.50
15	PROTECTION FILM-RH (NEC) <i>mu /</i>	1				\$ 20.50
16	FIXING DEVICE (NEC) <i>mu /</i>	2				\$ 50.00
17	GUIDE PLATE FOR BUMPER (NEC) <i>mu /</i>	2				\$ 29.80
18	RIVET (NEC) <i>mu /</i>	8				\$ 12.80
19	ADDITIONAL HEADLAMP LH <i>X</i>	1				\$ 437.30
20	ADDITIONAL HEADLAMP RH <i>X</i>	1				\$ 437.30
21		0				\$ -
TOTAL PARTS						\$ 5,177.90
TOTAL PARTS COST						\$ -
SUPPLEMENTARY						\$ 5,177.90

NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							
2							
3							
Labour Description							
1	TO REMOVE /REPLACE FORNT BUMPER, REINFORCEMENT & ALL DAMAGED BODY PARTS. TO					1560	\$ 3,120.00

	REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.				
	TO RESPRAY FRONT BUMPER.		1300	\$	1,500.00
	TO SUPPLY FRONT LICENCE PLATE WITH CASING		NETT	\$	70.00
4	TO APPLY SPECIAL CERAMIC COATING. (PROCE TO BE ADVISE) ? make ?		NETT		
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150	\$	250.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		NETT	\$	600.00
7	SUNDRIES.		NETT	\$	20 50.00

TOTAL LABOUR		\$	-	\$	5,590.00
TOTAL PARTS		\$	-	\$	5,177.90
TOTAL		\$	-	\$	10,767.90
LESS EXCESS		\$	-	\$	-
TOTAL AFTER EXCESS		\$	-	\$	10,767.90
GST 7%		\$	-	\$	753.75
GRAND TOTAL		\$	-	\$	11,521.65

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rashu

Hp 90010068

3 days

P/P

Resy 64 paint

03/03/22 @ 10:00 hrs