

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

			ternationale Des Experts En A	Automo	bile CS3/A	SM21008939
	AXA INSURANCE	PTE LTD	F	Ref:	CSS/ASIVIZ I	000939/Gvc
	8 SHENTON WAY AXA TOWERSING		Г	Date:	25/06/2021	25/02/2022
			C	Code:	ASM	
١.		Policy Partic	ulars :- (THIRD PARTY (CLAIN	/ I)	
	Insured Veh.	SHC 7034X	Veh. Inspected		XE 3058D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03GBW	Excess (\$)		0.00	
	Assign From	CHEN XINYOU	Assign Date		25/00/2021	25/02/2022
2.		Vehicle	Particulars & Condition	n		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
		C	Conditions of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
١.	Description of Damages					
5.	General Information					
	Accident Date	21/08/2021	Inspection Date		26/08/2021	
	Survey held at	ENG SOON HUAT				
	Repairer	-				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					