

Your Ref : DHOM110164481803

Date: 30th Mar 2022

Our Ref : CS/UOI22001830/Atf3e2

M/s United Overseas Insurance Ltd

146 Robinson Road

#02-01 Uoi Building

Singapore 068909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKP 3883J
ACCIDENT ON 23/02/2022**

Instruction was received to inspect the vehicle Reg. No. SKP 3883J. The inspection was conducted on 28/02/2022 at the premises of M/s J-Mart Motor Pte Ltd, Blk 5 Defu Lane 10 #01-578 Defu Industrial Park C, Singapore 539186.

The following vehicle information was recorded:

Registration Number	: SKP 3883J
Make/Model	: Subaru WRX 4D 2.0 AWD CVT SR
Year of Registration	: 2017
Body Colour	: Blue
Chassis Number	: JF1VAGK85JG020255
Engine Capacity	: 1998 cc
Speedometer Reading	: Nil

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 116,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 48,096.00)
Nett Liability	<u>S\$ 67,904.00</u> =====

Vehicle Inspected By:



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser



K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),

MASME(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIE(mech), MinstAEA, MFIEA,

MIRTE,MIMI,MSAE,MCIAd, AM,NIIJAAR(USA),

AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.