



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: LOH CHEE HENG			Ref: CS3/AIG21011775/Vqf3e2-1 Date: 08/03/2022 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 1769C	Veh. Inspected	SLT 4267Z	
Policy No.	1900017303	Coverage (\$)	0.00	
Claim No.	2459115250SG	Excess (\$)	0.00	
Assign From	LOH CHEE HENG	Assign Date	28/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED 1.5G	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GB71040464	Colour	RED	
Odometer	120040 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	DUNLOP	6 mm	
L/H Front Tyre	185/65 R15	DUNLOP	6 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2021	Inspection Date	23/11/2021	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	