

MSAO Tony

AUTOWERKS

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

28 February 2022

REG NO.: SND 8579 H
MAKE/MODEL: BMW 523i

Not Authorized
den
28/2/22
2/s #2700 /
3 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Rear boot lid R	\$ 1,658.00 X
2	Rear boot lamps nn	\$ 780.00 X
1	Rear boot lock nn	\$ 272.50 X
1	Rear boot logo nn	\$ 79.00 X
2	Rear taillamps nn	\$ 1,310.00 X
1	Rear end panel R	\$ 1,018.50 X
1	Rear end panel inner garnish nn	\$ 289.00 X
1	Rear bumper Dis	\$ 1,495.00
1	Rear bumper inner frame garnish Cne 182.30	\$ 335.00
1	Rear bumper lower se	\$ 685.00
2	Rear bumper side holders nn	\$ 278.60 X
4	Rear bumper PDC sensors shocked 182	\$ 1,436.00 1pc
1	Control module for park assistant kit nn	\$ 345.00 X
1	Rear exhaust silencer nn	\$ 1,980.00 X
4	Rear exhaust chrome tail pipes su	\$ 740.00 X
		\$ 9,636.60
	Less 5%	\$ 481.83
		\$ 9,154.77

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set) nee	\$ 80.00 60
		\$ 80.00

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 150.00 80
3	To remove and refit rear reverse sensor.	\$ 150.00 50
4	To transfer boot lid mechanism and wiring assembly.	\$ nn 120.00 X
5	To remove, refit and replace exhaust silencer and mountings.	\$ nn 180.00 X
6	To apply undercoating.	\$ nn 150.00 X
7	Panel beating.	\$ 1,500.00 300
8	To re-spray painting on the affected areas.	\$ 1,400.00 500
		\$ 3,730.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during **GRAND TOTAL:**
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 12,964.77

P- 2547.30

52

P- 2419.93

S.N - 60

L - 950

3429.93
2747