

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI22001856/Aqf3n2
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Г	Date:	12/05/2022
			C	Code:	AGI
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJG 5462L	Veh. Inspected		SLN 8476S
	Policy No.		Coverage (\$)		0.00
	Claim No.	C10014029 /EE	Excess (\$)		0.00
	Assign From	SHAFAWATI	Assign Date		28/02/2022
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 3	c.c		1496
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	JM6BN22A8H0146875	Colour		SILVER
	Odometer	61106 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	YOKOHAMA		6 mm
	L/H Front Tyre	205/60 R16	YOKOHAMA		6 mm
	R/H Rear Tyre	205/60 R16	YOKOHAMA		6 mm
	L/H Rear Tyre	205/60 R16	YOKOHAMA		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/02/2022	Inspection Date		02/03/2022
	Survey held at	YSK AUTO WORKSHOP			
		1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: