



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY		Ref: CC4/ASM22001867/Upa3q2 Date: 17/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHF 743M	Veh. Inspected	FBK 3975K
Policy No.	P2459880	Coverage (\$)	0.00
Claim No.	S2M03U8G	Excess (\$)	0.00
Assign From		Assign Date	28/02/2022
2. Vehicle Particulars & Condition			
Make & Model	K.T.M. 200 DUKE	c.c	200
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VBKJUC404EC027646	Colour	BLACK
Odometer	69496 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70Z R17	BRIDGESTONE	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60Z R17	BRIDGESTONE	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S & O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/02/2022	Inspection Date	28/02/2022
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	