



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22001877/Ktf3n2 Date: 23/05/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SND 2079Z	Veh. Inspected	FBP 94X
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22003966GK	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	28/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CB400	c.c	399
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	NC421901706	Colour	METALLIC BLUE
	Odometer	17756 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/60 ZR17	MICHELIN	3 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	160/60 ZR17	MICHELIN	3 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/02/2022	Inspection Date	01/03/2022
	Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	