

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	25 Feb 2022 19:34	Clm Veh Model Changed		[] Merimen Administrator
2	25 Feb 2022 19:34	Clm Created	Reg No: SMX8267P. Policy No: 7210004265-01. Acct Date: 2022/02/24. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SPOR222P0002	[I] Merimen Administrator
3	01 Mar 2022 10:35	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	01 Mar 2022 10:35	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	01 Mar 2022 10:35	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	01 Mar 2022 10:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/03/10	[A] CELINE FONG
7	01 Mar 2022 10:35	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	01 Mar 2022 10:35	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	01 Mar 2022 10:35	Clm Veh Model Changed	(205279) AUDI A5 2.0 SPORTBACK (A).	[A] CELINE FONG
10	01 Mar 2022 10:36	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
11	01 Mar 2022 11:10	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	01 Mar 2022 11:10	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	01 Mar 2022 11:10	Clm Dtl Modified	JPJ Reg. Date: -> 2021/01/30.	[A] Elaine Kuan Hwa Meen
14	01 Mar 2022 11:10	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	01 Mar 2022 15:59	Clm Registration Modified	Init.Est.:->5,000 - 6,000. 2F Remarks: -> Inexperience Driver. GST: -> 7.00.	[I] Azlan, Syazairdina
16	01 Mar 2022 17:02	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/03/10	[A] SHIAU CHAN

AUDIT TRAIL

No.	On Audit	Remarks	By
17	01 Mar 2022 17:03 Adj Mandate Request	Cur.Req:19408.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE N OT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	02 Mar 2022 13:00 Clm Registration Modified	Acct Time:18:45:00->18:00:00.	[I] AIG OneClaim Integration User
19	02 Mar 2022 13:31 Clm Registration Modified	Excess: -> 3800.00. Excess Waived: -> 800.00.	[I] Azlan, Syazairdina
20	02 Mar 2022 16:23 Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/03/10. Mandate Remarks: Vehicle may commence repair - Front Rim not consistent, to remove. Front RH tyre to retake damage photos and upload. Checked and Supplementary items to resurvey with CLEAR photos for da ma	[I] Lim, Kok-Chong
21	02 Mar 2022 16:23 Adj Mandate Set	Approved:15557.00:Vehicle may commence repair - Front Rim not consistent, to rem ove. Front RH tyre to retake damage photos and upload. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before p	[I] Lim, Kok-Chong

Date From



Date To



Audit Type

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2770149	01 Mar 2022 11:10:44	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMX8267P		11.00