

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



Denise.

DATE : 07.03.2022

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SJK9352Z
MODEL : MIT-LANCER
DATE OF ACCIDENT : 26.02.2022
TIME OF ACCIDENT : 09:45HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL NETT PRICE
1	FRONT BUMPER <i>Rehd</i>	1	\$ 898.00	\$ 898.00
2	FRONT BUMPER GRILLE LOGO <i>3HP</i>	1	\$ 57.00	\$ 57.00
3	FRONT BUMPER UPPER GRILLE <i>1m</i>	1	\$ 369.00	\$ 369.00
4	FRONT BUMPER UPPER GRILLE CHROME <i>He m</i>	1	\$ 284.00	\$ 284.00
5	FRONT BUMPER LOWER GRILLE <i>He m</i>	1	\$ 168.00	\$ 168.00
6	FRONT BUMPER LOWER GRILLE CHROME <i>He m</i>	1	\$ 237.00	\$ 237.00
7	FRONT BUMPER FOG LAMP COVER <i>RH cut</i>	2	\$ 39.00	\$ 78.00
8	FRONT BUMPER TOP RUBBER <i>He m</i>	1	\$ 38.00	\$ 38.00
9	FRONT BUMPER TOWING COVER <i>He m</i>	1	\$ 36.00	\$ 36.00
10	FRONT BUMPER SIDE RETAINER <i>RH Dented</i>	2	\$ 39.00	\$ 78.00
11	FRONT BUMPER REINFORCEMENT <i>2</i>	1	\$ 469.00	\$ 469.00
12	FRONT BUMPER BRACKET <i>1HP</i>	2	\$ 28.00	\$ 56.00
13	FRONT BUMPER TOP BEAM <i>1m</i>	1	\$ 135.00	\$ 135.00
14	FRONT BUMPER UNDER COVER GARNISH <i>He m</i>	1	\$ 198.00	\$ 198.00
15	FRONT ENGINE SIDE UNDER COVER GARNISH <i>He m</i>	2	\$ 78.00	\$ 156.00
16	FRONT FENDER <i>Dented RH</i>	2	\$ 698.00	\$ 1,396.00
17	FRONT FENDER CORNER COVER GARNISH <i>He m</i>	2	\$ 69.00	\$ 138.00
18	FRONT FENDER COWLING <i>He m torn RH</i>	2	\$ 136.00	\$ 272.00
19	BONNET <i>Dented</i>	1	\$ 899.00	\$ 899.00
20	BONNET STOPPER <i>He m</i>	2	\$ 34.00	\$ 68.00
21	BONNET WEATHER STRIP (INNER) <i>He m</i>	2	\$ 39.00	\$ 78.00
22	BONNET INSULATOR <i>He m</i>	1	\$ 198.00	\$ 198.00
23	BONNET LOCK <i>He m</i>	1	\$ 145.00	\$ 145.00
24	BONNET HINGE <i>Best</i>	2	\$ 58.00	\$ 116.00
25	HEADLAMP <i>RH cracked</i>	2	\$ 896.00	\$ 1,792.00
26	HEAD LAMP PANEL <i>Repair</i>	2	\$ 179.00	\$ 358.00

760
+
+
+
+
+
39.
+
+
39.
+
+
+
+
+
698.
+
136
-
+
+
+
+
896
x

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJK9352Z
 MODEL : MIT-LANCER
 DATE OF ACCIDENT : 26.02.2022
 TIME OF ACCIDENT : 09:45HRS

27	HEAD LAMP LOWER CLIPS <i>NEC</i>	2	\$ 41.00	\$ 82.00 <i>10</i>
28	FRONT SUPPORT PANEL <i>Regis</i>	1	\$ 487.00	\$ 487.00 <i>+</i>
29	FRONT SUPPORT PANEL TOP COVER GARNISH <i>pen</i>	1	\$ 145.00	\$ 145.00 <i>+</i>
30	WIPER WASHER TANK <i>Rehnd</i>	1	\$ 110.00	\$ 110.00 <i>✓</i>
31	ABS SENSOR	1	\$ 333.00	\$ 333.00 <i>+</i>
32	FRONT ANTI ROLL BAR LINKAGE	2	\$ 116.00	\$ 232.00 <i>+</i>
33	FRONT KNUCLE ARM	2	\$ 398.00	\$ 796.00 <i>+</i>
34	FRONT KNUCLE BEARING	2	\$ 184.00	\$ 368.00 <i>+</i>
35	FRONT WHEEL HUP <i>HP</i>	2	\$ 296.00	\$ 592.00 <i>+</i>
36	FRONT SHOCK ABSORBER	2	\$ 387.00	\$ 774.00 <i>x</i>
37	FRONT LOWER ARM	2	\$ 429.00	\$ 858.00 <i>+</i>
38	FRONT STEERING RACK AND PINION <i>✓</i>	1	\$ 1,765.00	\$ 1,765.00 <i>+</i>

3703

TOTAL PRICE \$ 15,259.00

LESS 10% \$ 1,525.90

3332.70

SUB TOTAL PRICE \$ 13,733.10

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Not nec</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
2	FRONT BUMPER CLIP (SET) <i>Not nec</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
3	FRONT BUMPER UNDER COVER GARNISH CLIP (SET) <i>Not nec</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
4	FRONT ENGINE SIDE UNDER COVER GARNISH RH CLIP (SET) <i>Not nec</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
5	FRONT FENDER CORNER COVER GARNISH CLIP (SET) <i>Not nec</i>	1	\$ 40.00	\$ 40.00 <i>+</i>
6	FRONT FENDER COWLING CLIP (SET) <i>Not nec</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
7	BONNET INSULATOR CLIP (SET) <i>Not nec</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
8	FRONT SUPPORT PANEL SEALANT <i>Not nec</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
9	FRONT SUPPORT PANEL TOP COVER GARNISH CL <i>Not nec</i>	1	\$ 40.00	\$ 40.00 <i>+</i>
10	REAR FENDER INNER COWLING CLIP (SET) <i>Not nec</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
11	REAR FENDER INNER TRIM CLIP (SET) <i>Not nec</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
12	WHEEL TYRE <i>Not nec</i>	1	\$ 380.00	\$ 380.00 <i>+</i>
13	WHEEL RIM <i>Not</i>	1	\$ 850.00	\$ 850.00 <i>700</i>
14	WHEEL CAP (SET) <i>Not nec</i>	1	\$ 120.00	\$ 120.00 <i>+</i>
15	RADIATOR COOLANT <i>Not nec</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
16	BRAKE OIL <i>Not nec</i>	1	\$ 50.00	\$ 50.00 <i>+</i>

TOTAL \$ 2,110.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJK9352Z
 MODEL : MIT-LANCER
 DATE OF ACCIDENT : 26.02.2022
 TIME OF ACCIDENT : 09:45HRS

1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 2,000.00	700
2	TO SPRAY PAINT	\$ 1,800.00	800
3	WIRING, BULB CHECKING	\$ 80.00	30
4	REFOCUS HEADLAMP BEAM	\$ 60.00	+
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	+
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	+
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	+
10	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	+
11	FOUR WHEEL ALIGNMNET	\$ 120.00	80
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL 1610 \$ 5,440.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,843.10
 TOTAL LABOUR COST : \$ 5,440.00
 TOTAL REPAIR COST : \$ 21,283.10

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE
 SERVICE ADVISOR
 IRENE
 HP :8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total: 5402.70

h/s: 43K

4.310

Adrian Lj
 h/s 07/03/22
 05 Days