

					COMINORIDELORG		
Our Job Ref No :			305506818		ENGINEERING		
Date : 03/03/22					ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
FIN	ALIZAT	ION FORM				:: 6546 8156	
То	:		LKK		Fax :		
Attn : TAUFIKH							
Vehicle Reg No. : SHB4333H						26/02/2022	
The	survey	and estimates of	the repairs of the above-me	entioned vehicle	e are as follow	/s:-	
Z	The repair job shall bill to:			NTUC	NTUC GBF5431B		
2.	The finalized amount shall be:						
۷.	(a)		er List discount				
	(α)	opare i arts art	er List discount			9	
	(b)	Labour Charge	s				
		Total for Part-	By-Part Repair Cost				
	(c.)	Lumpsum Repa	air (if applicable)				
	(,	Total for Lumpsum repair cost after Less:			=1	2	
	Final Lumpsum Repair cost					\$1,700.00	
3	Estim	nated normal peri	nd for renairs:	<b>2</b> wo	orkina dave		
4.	We s	hall treat the aboing days	ove amount as Correct and	d Confirmed if	there is no re	eply from you within 7	
5.	5. Thank you for your assistance.				We confirm the estimates and finalized amount		
					anzoa amoun	•	
			(1)				
	Signature :			_ Sig	Signature: taufik		
Name : CHIANG			Na	Name : Taufikh			
Tel : 62148314			Da	Date : 22/3/22			
	Fax	6546815	6				
For C	Official	Use Only					
				Document	6 6 5		
	1	ltem	Amount	Attached Yes or No	Confirm By (Signature)	Remarks	
Rental Rate P/Day				YES			
Loss of Income Paid				N			
3. Survey Fees			24	4			
4. LTA Search Fee			\$7.49/\$2.00				
<ol><li>Medical Fees (on behalf of driver, if applicable)</li></ol>		ees (on behalf					
6 Overrun							

Remarks: