

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0140/2022/JT
DATE : 28-Feb-22
WIP : 13517

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS CHUA SOCK KOONG
ADDRESS : 15A OEI TIONG HAM PARK
SINGAPORE 268302
TELEPHONE : HP +65 96788385
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900012064-02
VEHICLE NO : SKC 900 G
MODEL CODE : AUDI Q7 2.0 TFSI QU
MODEL YEAR : 26/2/2022
ENGINE NO : CYR 070461
CHASSIS NO : WAUZZZ4M6JD061097
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Feb-22
PLACE OF ACCIDENT : CLEMENTI AVENUE 3 RIGHT TURNING
OUT OF BLK 428

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 900 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEALIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, S/N \$ HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00 /	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N \$	450.00 /	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. S/N \$ 550 x 2	2,700.00	1100
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER. S/N \$	2,500.00	1000
5	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	192.00 /	
TOTAL LABOUR CHARGES		: \$ 6,322.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 900 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER ✓ CRu	1	\$ 2,896.00	
2	FRONT BUMPER FIXING PARTS X	1	\$ 468.00	
3	FRONT BUMPER AIR GUIDE - LH / RH ?	1	\$ 75.00	
4	FRONT BUMPER END CAP - LH ?	1	\$ 40.00	
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER ?	1	\$ 309.00	
6	FRONT BUMPER GRILLE - LOWER CENTER X	1	\$ 230.00	
7	FRONT BUMPER UNDERRUN BAR X	1	\$ 899.00	
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER X	1	\$ 235.00	
9	FRONT BUMPER SPOILER - LH X	1	\$ 154.00	
10	FRONT BUMPER SPOILER - LH OUTER X	1	\$ 49.00	
11	RADIATOR GRILLE X	1	\$ 2,741.00	
12	RADIATOR GRILLE INNER COVER X	1	\$ 69.00	
13	RADIATOR GRILLE UPPER COVER X	1	\$ 81.00	
14	FRONT BUMPER AIR GUIDE GRILLE - LH ✓ MIS	1	\$ 332.00	
15	FRONT BUMPER END CAP - LH ✓ HIC	1	\$ 38.00	
16	SPRING CLIP - LH ?	4	\$ 4.00	
17	RADIATOR SPOILER - INNER LH X	1	\$ 64.00	
18	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 192.00	
19	FRONT BUMPER REINFORCEMENT BEAM X	1	\$ 1,025.00	
20	FRONT BUMPER SUPPORT - LH / RH ?	2	\$ 81.00	
SUB TOTAL SPARE PARTS		:	\$ 9,982.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 900 G

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER GUIDE SECTION UPPER - LH ?	1	\$ 50.00	
22	FRONT BUMPER TOP COVER X	1	\$ 146.00	
23	"CAUTION" STICKER X	1	\$ 16.00	
24	AIR COND STICKER X	1	\$ 9.00	
25	HORN BRACKET - LH ?	1	\$ 240.00	
26	FRONT PARKING AID SENSOR - INNER / OUTER X	2	\$ 488.00	
27	FRONT PARKING AID SENSOR SEAL RING X	4	\$ 10.00	
28	FRONT FENDER - LH / ON (Aluminum) X	1	\$ 1,819.00	
29	FRONT FENDER ATTACHMENT PARTS X	1	\$ 79.00	
30	FRONT FENDER BRACE - LH ?	1	\$ 120.00	
31	FRONT FENDER BRACKET - LH ?	1	\$ 72.00	
32	FRONT WHEEL HOUSING LINER - LH X	1	\$ 260.00	
33	REAR WHEEL HOUSING LINER - LH X	1	\$ 260.00	
34	HEADLIGHT MOUNTING - LH ?	1	\$ 132.00	
35	HEADLIGHT - LH / BR	1	\$ 10,660.00	
36	LIFT CYLINDER - LH ?	1	\$ 217.00	
37	LIFT CYLINDER HOSE - LH ?	1	\$ 113.00	
38	OUTSIDE TEMPERATURE SENSOR BRACKET X	1	\$ 5.00	
39	RADIATOR AIR GUIDE - LH X	1	\$ 33.00	
40	RADIATOR AIR GUIDE - UPPER X	1	\$ 48.00	
SUB TOTAL SPARE PARTS		:	\$ 14,777.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 900 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	RADIATOR AIR GUIDE - LOWER X	1	\$	48.00	
42	FRONT WHEEL ARCH COVER - LH / RH ✓ NC	2	\$	696.00	
43	FRONT NO PLATE X	S/N	\$	60.00	
44	SUNDRIES ↑		\$	300.00	
TOTAL SPARE PARTS		:	\$	25,863.00	
TOTAL LABOUR CHARGES		:	\$	6,322.00	
GRAND TOTAL		:	\$	32,185.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



ROAD 1, SINGAPORE 408699
666 2323 FAX: 6841 1183
E: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Steve (CLK)
:
: 1/3/12, 12.09pm
:
: 4 dys
: 00-M AL
: EXCESS ? , P/P, My BL y

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT