



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM <i>Vehicle Grounded</i> <i>Liability Check</i> <i>At New Scheme</i>			S1000020 / TPCLAIM		Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153			
			Document No.					
			0					
			Document Date					
			28/02/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3701191537		2NR5399835	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SMC3498H ACC DATE:28/02/2022 TP INS: NO.OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM						30.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR BONNET						60.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME						180.00
4	B	BP-MECH2 R/I AIRCON CONDENSER/RADIATOR TO FACILITATE REPAIRS.						360.00
5	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.						122.40
6	B	BP-LAB2 TO REPLACE FRONT ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.						4320.00
7	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.						3540.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR BOOTLID AND REAR END PANEL.						120.00
9	B	BP-LAB2 TO CONDUCT WATER LEAK TEST.						122.40
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy



Borneo Motors


Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM		Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153				
		Document No.						
		0						
		Document Date						
28/02/2022								
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3701191537		2NR5399835	60	Raymond Seah L M	--/--/----	0.00	--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS.						180.00
11	B	BP-LAB2 R/I REAR CARPET,TRIMMING AND OTHER ATTACHMENT TO FACILIATE REPAIRS.						360.00
12	B	BP-LAB2 TO TRANSFER REAR BOOTLID MECHANISM AND COMPONENT TO NEW PANELS.						360.00
13	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS						4320.00
14	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.						3540.00
15	1	S81110-0DF50	HEADLAMP ASSY, RH	1.00	1668.80		1668.80	
16	2	S81150-0DF50	HEADLAMP ASSY, LH	1.00	1668.80		1668.80	
17	3	S85315-0D220	JAR, WASHER, A	1.00	154.60		154.60	
18	4	S88300-0D530	AIR CON KIT (NEW VIOS 2016)	1.00	3026.60		3026.60	
19	5	S08889-80102	COOLANT,SLLC&&&	2.00	84.30		168.60	
20	6	S16400-0Y191	RADIATOR ASSY	1.00	2176.50		2176.50	
21	7	S53112-0D650	GRILLE, RADIATOR, LW	1.00	387.30		387.30	
22	8	S53113-0D020	GRILLE, RADIATOR, LW	1.00	96.60		96.60	
23	9	S52119-0U932	COVER, FR BUMPER, L	1.00	525.80		525.80	
24	0	S52161-0K040	CLIPS	4.00	4.30		17.20	
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd								
		Please acknowledge receipt of vehicle		Parts		Less		
				Labour				
				Sublet				
				Lubrication/Fluid				
				Others		Amount Due		

Customer Copy



Borneo Motors


Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details						
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153						
		Document No. 0							
		Document Date 28/02/2022							
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MR2B23F3701191537		2NR5399835	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
25	1	S52535-0D230	RETAINER, FR BUMPER			1.00	106.70		106.70
26	2	S52536-0D230	RETAINER, FR BUMPER			1.00	106.70		106.70
27	3	T90467-05170	CLIP			2.00	2.70		5.40
28	4	T47749-33030	CLIP, PIN HOLD			2.00	9.20		18.40
29	5	T53879-33030	RETAINER, FR FENDER			2.00	12.80		25.60
30	6	S52021-0D140	REINFORCEMENT SUB-AS			1.00	423.90		423.90
31	7	S53111-0D912	GRILLE, RADIATOR, OU			1.00	75.40		75.40
32	8	S53123-0D050	MOULDING, RADIATOR G			1.00	73.40		73.40
33	9	S53124-0D040	MOULDING, RADIATOR G			1.00	73.40		73.40
34	0	S53119-0D010	PROTECTOR, RADIATOR			1.00	15.50		15.50
35	1	T53119-12150	FRT GRILLE CUSHION,			1.00	20.90		20.90
36	2	S90975-T2008	EMBLEM, SYMBOL			1.00	61.90		61.90
37	3	S53301-0D280	HOOD SUB-ASSY			1.00	982.10		982.10
38	4	S53510-0D770	LOCK ASSY, HOOD			1.00	143.70		143.70
39	5	S53410-0D400	HINGE ASSY, HOOD, RH			1.00	62.40		62.40
40	6	S53420-0D400	HINGE ASSY, HOOD, LH			1.00	62.40		62.40
41	7	S53141-0D040	COVER, RADIATOR			1.00	290.40		290.40
42	8	T90467-07217	CLIP			10.00	2.70		27.00
43	9	S53208-0D901	SUPPORT SUB-ASSY, HO			1.00	159.30		159.30
44	0	S53210-0D929	SUPPORT ASSY, RADIAT			1.00	1034.50		1034.50
For & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts		Less			
				Labour					
				Sublet					
				Lubrication/Fluid					
				Others		Amount Due			

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM		Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153				
		Document No.						
		0						
		Document Date						
28/02/2022								
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3701191537		2NR5399835	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
45	1	S53213-0D161 SUPPORT, RADIATOR, U			1.00	83.60		83.60
46	2	S53214-0D161 SUPPORT, RADIATOR, U			1.00	83.60		83.60
47	3	S53285-0D370 SEAL, RADIATOR SIDE			1.00	84.70		84.70
48	4	S53286-0D370 SEAL, RADIATOR SIDE			1.00	84.70		84.70
49	5	S53287-0D260 EXTENSION, RADIATOR			1.00	68.40		68.40
50	6	S53288-0D250 EXTENSION, RADIATOR			1.00	76.60		76.60
51	7	SPC507-0D015 43 BACK SENSOR 218 ATTITUDE BLACK			1.00	198.50		198.50
52	8	TAUTOF-J3W11 BACK CAMERA			1.00	217.85		217.85
53	9	S81550-0DA41 LAMP ASSY, RR			1.00	676.20		676.20
54	0	S81560-0DA41 LAMP ASSY, RR			1.00	676.20		676.20
55	1	S52562-0D130 RETAINER, RR BUMPER,			1.00	63.40		63.40
56	2	S52563-0D130 RETAINER, RR BUMPER,			1.00	63.40		63.40
57	3	T81496-60010 REAR LAMP GUIDE,			2.00	3.70		7.40
58	4	S81497-0D070 COVER, RR COMBINATIO			2.00	3.50		7.00
59	5	S81580-0D490 LAMP ASSY, RR, RH			1.00	438.10		438.10
60	6	S81590-0D490 LAMP ASSY, RR, LH			1.00	438.10		438.10
61	7	S81910-0D050 REFLECTOR ASSY, REFL			1.00	99.80		99.80
62	8	S81920-0D050 REFLECTOR ASSY, REFL			1.00	99.80		99.80
63	9	T89997-30100 ANTENNA, ELECTRICAL			1.00	76.30		76.30
64	0	S52159-0U963 COVER, RR BUMPER L/C			1.00	557.70		557.70
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts		Less		
				Labour				
				Sublet				
				Lubrication/Fluid				
				Others				
						Amount Due		

Customer Copy



Borneo Motors


Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM		Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153				
		Document No.						
		0						
		Document Date						
28/02/2022								
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3701191537		2NR5399835	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
65	1	S75895-0D270 TAPE, MOULDING, NO.1			2.00	53.50		107.00
66	2	S52161-0K040 CLIPS			4.00	4.30		17.20
67	3	S52575-0D340 RETAINER, RR BUMPER			1.00	164.30		164.30
68	4	S52576-0D330 RETAINER, RR BUMPER			1.00	164.30		164.30
69	5	S52023-0D090 REINFORCEMENT SUB-AS			1.00	353.10		353.10
70	6	S58311-0D111 PAN, RR FLOOR			1.00	739.90		739.90
71	7	S58307-0D480 PANEL SUB-ASSY, BODY			1.00	786.30		786.30
72	8	S58387-0D200 PLATE, RR FLOOR FINI			1.00	295.40		295.40
73	9	T90467-08186 C3 CLIP			2.00	2.60		5.20
74	0	S64770-0D380 COVER ASSY, SPARE WH			1.00	322.90		322.90
75	1	S64401-0D360 PANEL SUB-ASSY, LUGG			1.00	838.90		838.90
76	2	S64461-0D180 WEATHERSTRIP, LUGGAG			1.00	186.50		186.50
77	3	S64600-0D040 LOCK ASSY, LUGGAGE C			1.00	423.90		423.90
78	4	S75431-02090 LUGGAGE COMP EMBLEM,			1.00	65.30		65.30
79	5	S75442-0D400 PLATE, LUGGAGE COMPT			1.00	48.30		48.30
80	6	S75444-0D700 PLATE, LUGGAGE COMPT			1.00	37.60		37.60
81	7	S76801-0D870 GARNISH SUB-ASSY, BA			1.00	65.20		65.20
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						39,997.25		
		Please acknowledge receipt of vehicle		Parts		22,382.45		
				Labour		17,614.80		
				Sublet		0.00		
				Lubrication/Fluid		0.00		
				Others		0.00		
				GST 7.00%		2,799.81		
				Less		0.00		
				Amount Due		42,797.06		

Customer Copy