

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile							
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO22001925/Aty3n2			
	50 RAFFLES PLAC SINGAPORE LAND	E #03-03) TOWERSINGAPORE 048623	Date:	29/04/2022			
			Code:	SMO			
1.	Policy Particulars :- THIRD PARTY CLAIM						
I	Insured Veh.	SND 9914S	Veh. Inspected	SML 2152P			
F	Policy No.		Coverage (\$)	0.00			
	Claim No.	CMTD2200744/THE	Excess (\$)	0.00			
	Assign From	GRACE TEO	Assign Date	01/03/2022			
2. Vehicle Particulars & Condition							
	Make & Model	HONDA FREED HYBRID	c.c	1496			
E	Engine No.	HIDDEN	Year of Reg.	2019			
	Chassis No.	GB71080696	Colour	SILVER			
	Odometer	49166 KM	Steering	IN ORDER			
E	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3. Conditions of Tyres							
		Size	Make	Balance			
F	R/H Front Tyre	205/45 R17	GOODYEAR	6 mm			
L	L/H Front Tyre	205/45 R17	GOODYEAR	6 mm			
F	R/H Rear Tyre	205/45 R17	GOODYEAR	6 mm			
L	L/H Rear Tyre	205/45 R17	GOODYEAR	6 mm			
4.							
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.						
	DAMAGES SEE DETAILS.						
5.	General Information						
	Accident Date	25/02/2022	Inspection Date	01/03/2022			
	Survey held at	JEC AUTO SERVICE PTE LTD					
		1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883					
5a.	Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
	B)III ACCONDAINC			Estimate Days of Repair			
	B)IN ACCORDANC	· · · · · · · · · · · · · · · · · · ·	Days of Repair				