



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22001931/Rvy3e2	
			Date: 09/05/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 5279P	Veh. Inspected	SMQ 2338U
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000595MFCV	Excess (\$)	0.00
	Assign From	RACHEL WU	Assign Date	01/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 520I	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WBAJR12070WW55439	Colour	GREY
	Odometer	47774 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45Z R18	HANKOOK	6 mm
	L/H Front Tyre	245/45Z R18	HANKOOK	6 mm
	R/H Rear Tyre	245/45Z R18	HANKOOK	6 mm
	L/H Rear Tyre	245/45Z R18	HANKOOK	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/02/2022	Inspection Date	02/03/2022
	Survey held at	39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS		
	Repairer	YEW TEE AUTOMOBILE TECH PL (HQ)		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	