

BIFROST AUTO PTE LTD

SUPPLEMENTARY REPAIR ESTIMATE (S)

DATE: 3-Mar-22

MODEL: HYUNDAI I40

INSURANCE: AUTO & GEN

VEHICLE NO.: SHC 8764 R

DESCRIPTION	QTY	LIST PRICE	AMOUNT
HEADLAMP (RH) <i>monity broken</i>	1	\$2,776.00	\$2,776.00 ✓
SUB TOTAL			\$2,776.00
LESS 20%			\$555.20
DISCOUNTED TOTAL			\$2,220.80
ESTIMATE TOTAL			\$2,220.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1388.2

Gyan

2kk Auto

04/03/222

1110.40

8