

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	01 Mar 2022 11:31	Clm Veh Model Changed	(204865) BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A).	[R] DORLYN LI YAZHU
2	01 Mar 2022 11:31	Clm Created	Reg No: SMX837Y. Policy No: MPC22A00011700. Acct Date: 2022/02/24. Claim Type: OD. Insurer: ECICS Limited (HQ). Workshop: Cheng Hoe Motor Pte Ltd (Yishun)	[R] DORLYN LI YAZHU
3	01 Mar 2022 14:05	Clm Submitted	36688.00.	[R] DORLYN LI YAZHU
4	01 Mar 2022 16:10	Clm Registration Modified	Excess: -> 3750.00.	[I] Crystabelle Tan
5	01 Mar 2022 16:10	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ);; RR Region: ECICS EXT ADJ - OD/TP. Suggested Adj. : LKK Auto Consultants Pte Ltd.	[I] Crystabelle Tan
6	01 Mar 2022 16:10	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/03/10	[I] Crystabelle Tan
7	01 Mar 2022 16:10	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Crystabelle Tan
8	01 Mar 2022 16:14	Assignment 1st Accessed		[A] NA MENG YAN
9	01 Mar 2022 17:48	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] NA MENG YAN
10	03 Mar 2022 09:02	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
11	03 Mar 2022 10:34	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/03/10	[A] SHIAU CHAN
12	03 Mar 2022 10:35	Adj Mandate Request	Cur Req:36468.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. THE VEHICLE REPAIR ON LUMP SUM BASIS. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	04 Mar 2022 14:01	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/03/10	[I] Crystabelle Tan
14	04 Mar 2022 14:01	Adj Mandate Set	Approved:19500.00.	[I] Crystabelle Tan
15	23 Mar 2022 11:17	Clm Supp Created	(S:1077178)	[R] DORLYN LI YAZHU
16	23 Mar 2022 11:21	Clm Submitted	1182.50. (S:1077178)	[R] DORLYN LI YAZHU
17	23 Mar 2022 11:21	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ): (S:1077178)	[R] Merimen Administrator
18	23 Mar 2022 14:58	Supp Combined	(S:1077178)	[A] SHIAU CHAN
19	23 Mar 2022 15:04	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/03/10	[A] SHIAU CHAN
20	23 Mar 2022 15:05	Adj Mandate Request	Cur Req:37650.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
21	23 Mar 2022 19:37	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/03/10. Mandate Remarks: Lump sum repair at \$37,650.50?	[I] Crystabelle Tan

AUDIT TRAIL				
No.	On	Audit	Remarks	By
22	23 Mar 2022 19:37	Adj Mandate Set	Maintained:Lump sum repair at \$37,650.50?	[I] Crystabelle Tan
23	24 Mar 2022 09:29	Adj Mandate Request	Cur Req:37650.50:The estimate Lump Sum repair cost is \$30,100.00 inclusive of check items.	[A] SHIAU CHAN
24	24 Mar 2022 15:57	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/03/10. Mandate Remarks: Able to negotiate lump sum at \$25K?	[I] Crystabelle Tan
25	24 Mar 2022 15:57	Adj Mandate Set	Maintained:Able to negotiate lump sum at \$25K?	[I] Crystabelle Tan
26	28 Mar 2022 12:47	Adj Mandate Request	Cur Req:25000.00:Dear Crystabelle, please be informed that we have checked with repairer, they agreed to repair the vehicle at \$25,000 on Lump Sum basis including further supplementary. kindly advise.	[A] SHIAU CHAN
27	28 Mar 2022 16:09	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/03/10. Mandate Remarks: Able to negotiate lump sum at \$25K?	[I] Liu Chun Cheong
28	28 Mar 2022 16:09	Adj Mandate Set	Approved:25000.00:Able to negotiate lump sum at \$25K?	[I] Liu Chun Cheong

Date From		 	Date To		 	Audit Type	None	 
------------------	----------------------	---	----------------	----------------------	---	-------------------	-----------------------------------	---

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2770165	01 Mar 2022 11:31:16	OD/TP Case (Repairer)	Motor	Cheng Hoe Motor Pte Ltd	Cheng Hoe Motor Pte Ltd (Yishun)	SMX837Y		xx.xx
2770169	01 Mar 2022 11:35:52	CMF LITE (OD)	TrueSight-CMF	ECICS Limited (HQ)	ECICS Limited (HQ)	SMX837Y	LIM PEI XIAN	xx.xx
2770741	03 Mar 2022 09:02:02	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMX837Y		11.00

