

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LIBERTY INSURAI	NCE PL		Ref:	CS/CWF22001964/Vvy3	
		& COMPANY INTERNATIONAL		Date:	02/03/2022	
	PTE LTD A 6 SHENTON WASINGAPORE 0688	AY, #19-10 OUE DOWNTOWN2, 09SINGAPORE 068809				
				Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	ł	SLV 4391L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	1095870/G/KY	Excess (\$)		0.00	
	Assign From	KENNETH YEE	Assign Date		02/03/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	07/02/2022	Inspection Dat	e	02/03/2022	
	Survey held at	CAR CITY AUTO CENTRE PTE	LTD			
		BLK 9006 TAMPINES ST 93 #01-198 SINGAPORE 528840				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					