



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H
 REPAIR PERFORMA INVOICE

FIRST CAPITAL

Vehicle number	GBK1687E
Make / Model	TOYOTA DYNA
Chassis number	JTFAT35YX0K214694
Accident date	1-3-22
Reference	2203-01

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT WING MIRROR LH	660.11 /scr
1	COOLING COIL	1637.79 /lt
		2297.90
	Less 25%	574.48
		1723.42
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	REAR NUMBER PLATE HOLDER	150.00 /DT
	Subtotal	150.00
	Balance C/F	1873.42
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	R&R COOLING COIL	200.00 SO
	Subtotal	200.00
	Grand total	2073.42

482 365
 114.1